



Raport Historii Pojazdu autoDNA

Raport zawiera dostępne informacje na dzień: 2022-11-04 14:16:41 UTC +0100

Wersja językowa: PL

3f5870dc-3b83880d-f9dfb3cf-7bf85dd5-6d4bb816



Kia OPTIMA
KNAGU815GH5160656

Wiek pojazdu

Wg daty produkcji / roku modelowego

5

LAT(A)

10

MIES.

Data produkcji / Rok modelowy 2017

Wg pierwszej rejestracji pojazdu

4

LAT(A)

10

MIES.

Data pierwszej rejestracji 2017-12-20

9 1 2 9 5 km

Uwaga: Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

CENTRUM POWIADOMIEŃ

Bazy Skradzionych Pojazdów



Przeszukane bazy 12/12

Akcje serwisowe



Nie odnotowano

Informacje o pojeździe



Liczba wpisów 18

Dziennik użytkowania



Liczba wpisów 9

Historia cenowa



Liczba wpisów 1

Odczyty drogomierza



Liczba wpisów 7

Historia uszkodzeń

 Liczba wpisów 2

Wyposażenie

 Liczba wpisów 404

Archiwalne zdjęcia

 Liczba wpisów 0

Poprawność VIN

 Niedostępne

INFORMACJE O POJEŹDZIE

Producent
KIA**Typ paliwa**
DIESEL**Rok modelowy**
2017**Próbka koloru lakieru**
**Silnik**
1.7L DOHC TCI**Kod modelu**
KEURPD416**Model**
OPTIMA**Pojemność silnika [cm3]**
1700**Kod koloru lakieru**
ABP**Kod koloru wnętrza**
WK**Skrzynia biegów**
7-BIEGOWA**Rynek przeznaczenia**
C07, GERMANY**Rodzaj nadwozia**
KOMBI**Kraj producenta**
KOREA POŁUDNIOWA**Kolor lakieru**
AURORA BLACK**Data produkcji**
2017**Napęd**
2WD**Średnie spalanie [l/100km]**
6.50

AKCJE SERWISOWE



Nie odnotowano

BAZA SKRADZIONYCH POJAZDÓW

Przeszukane bazy 12

Odnutowano 0

 **Włochy**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

 **Czechy**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

 Rumunia

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano **Litwa**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano **Słowenia**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano **Holandia**Ewidencja pojazdów skradzionych - Repozytoria
Crimimail oraz Stowarzyszenie Ubezpieczycieli Nie odnotowano **Kanada**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano **Słowacja**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano **Szwecja**Ewidencja pojazdów skradzionych - Stowarzyszenie
Ubezpieczycieli Nie odnotowano **Norwegia**

Ewidencja pojazdów skradzionych - Ettersøkt

 Nie odnotowano **Kaynine**Ewidencja przedmiotów skradzionych -
Kaynine(Niemcy) Nie odnotowano **Baza int.**Ewidencja pojazdów skradzionych - Niezależne
źródła internetowe Nie odnotowano

HISTORIA POJAZDU


2022**18.08.2022**Odnotowano cenę / wartość
77 900 PLN brutto**18.08.2022**

Zgłoszono odczyt drogomierza

Stan drogomierza
144 860 km**02.08.2022**Ubezpieczenie pojazdu
Polisa ważna do **2023-08-01**
Kraj **Polska**

02.08.2022

Pojazd zarejestrowany

Kraj poprzedniej rejestracji **Niemcy**
Homologowany fabrycznie
Używany, sprowadzony
Przystosowany do ciągnięcia przyczepy
 Kraj **Polska**

01.08.2022

Wykonano okresowe badanie techniczne

Wynik **Pozytywny**
 Termin badania technicznego **2023-08-01**
 Kraj **Polska**

Stan drogomierza
144 749 km

2021

04.01.2021

Serwis pojazdu

04.01.2021

Zgłoszono odczyt drogomierza

Stan drogomierza
118 091 km

2019

28.03.2019

Serwis pojazdu

28.03.2019

Zgłoszono odczyt drogomierza

Stan drogomierza
57 589 km

2018

08.2018

Odnotowano szkodę na pojeździe

Kwota **2500 - 3000 EUR**

Rezultat



USZKODZENIE NADWOZIA

Grupa części

- Elementy karoserii zewnętrznej
- Oświetlenie zewnętrzne



Strefa uszkodzenia
 - Przód
 - Lewy przód

12.02.2018

Kraj **Niemcy**

Serwis pojazdu

12.02.2018

Zgłoszono odczyt drogomierza

Stan drogomierza
7 325 km

02.2018

Zgłoszono odczyt drogomierza

Stan drogomierza
7 500 km

02.2018

Odnotowano szkodę na pojeździe

Kwota **4000 - 4500 EUR**

Rezultat



USZKODZENIE NADWOZIA

Grupa części

- Elementy karoserii zewnętrznej
- Elementy konstrukcyjne nadwozia
- Oświetlenie zewnętrzne



Strefa uszkodzenia

- Przód
- Prawy przód
- Lewy przód

Kraj **Niemcy**

2017

20.12.2017

Pierwsza rejestracja pojazdu

20.12.2017

Rozpoczęcie okresu gwarancyjnego

06.12.2017

Serwis pojazdu

06.12.2017

Zgłoszono odczyt drogomierza

Stan drogomierza
4 km

23.01.2017

Pojazd wyprodukowany

DZIENNIK SPRAWDZEŃ

Data i czas	Rodzaj usługi	IP	Lokalizacja
--	--	--	--

WYPOSAŻENIE

ONE TOUCH - FLAT FOLD HANDLE - LUGGAGE S85B5A1	DR SIDE W/STRIP - RUBBER(SILICON COAT'G)8212A1	BACK LITE GLASS TYPE - PRIVACY(W/ HEATED)8712C2
CLUSTER TYPE - SUPER VISION 4.2" TFT LCD9401D5	RETRACTOR PRETENSIONER - ELECTRICAL TYPE8885A2	CENTRAL DR LOCK/UNLOCK-DR"S & PA"S CTRL8131A2
STEER"G COLUMN-MANUAL TILT & TELESCOPIC5631A4	SEAT WARMER (HEATER) - 3-STEPS (BUTTON)8838B4	SEAT WARMER (HEATER) - 3-STEPS (BUTTON)8873B4
BODY SIDE W/STRIP-RUBBER(SILICON COAT'G)8211A1	DR BELT LINE MLD'G - BLACK-SUS+PVC TYPE8223A2	UPR TRIM FINISH'G - TPO (THERMO PLASTIC)8232A8
TAIL GATE FINISH"G-FORMED TYPE(PLASTIC)817AB3	TIRE PRESSURE MONITORG SYS - HIGH LINE9574A1	P/WINDOW RR DR - AUTO UP/DOWN & SAFETY824CA6
LWR TRIM (MAIN TRIM)PLASTIC(NO COVERG)82AB8A1	SIDE AIR BAG-FR - FR(THORAX & PELVIS)5693A3	RR WIPER - INTERMITTENT(NON VARIABLE)9871A1
ARM REST COVER"G - ARTIFICIAL LEATHER8236A3	SENSOR-AIR FLOWER - NON SPEED DENSITY3921A1	P/WINDOW PA'S - AUTO UP/DOWN & SAFETY824BA6
P/WINDOW DR"S - AUTO UP/DOWN & SAFETY824AA6	O.B.D(ON-BOARD DIAGNOSTICS) - E.O.B.D2845A2	BATTER CAPACITY AGM TYPE - 64AH (5HR)3711C3
W/ STORAGE BOX ARM REST - STD(1 DIN)846BA1	FUEL FILLER DR FINISH'G - BODY COLOR8153A1	POCKET LIGHTING - FRT DOOR - W/ILLUM826DA1
BUTTON START - BUTTON W/ ILLUMINATED8196A2	W/S GLASS TYPE-TINTED (W/ S/B,SOLAR)8611B3	MUFFLER MAIN ASSY - SINGLE-CR COAT"G2861A2
FR SUSP TYPE - MACPH. W/COIL SPRING5411A1	SEAT BACK - SEAT BACK PNL(W/POCKET)886BA3	AUTO LIGHT CONTROL SYSTEM - 1 STAGE9511A1
TEMPORARY - TIRE MOBILITY KIT (TMK)5297D1	SHIFT LOCK SYSTEM - ELECTRONIC TYPE4503A2	VSM (VEHICLE STABILITY MANAGEMENT)589CA1
FUEL FILLER DR REL TYPE - ELECTRIC8152A4	TAIL GATE OPEN'G DEVICE - GAS LIFT8173A1	CARRIER MATERIAL - PLASTIC(HYBRID)6411A1
SPEAKER LOCATION RR DR LOW-GENERAL963ZA1	TPMS (TIRE PRESSURE MONITORG SYS)94K3A1	FUEL FILLER DR MATERIAL - PLASTIC8151A2
DRIVER'S SIDE - ELECTRIC HTD-CONV8763C4	A/CLOTH(CLOTH+ARTIFICIAL LEATHER)8811B4	FR WIPER - INTERMITTENT(VARIABLE)9811A2
TRUNK LID RELEASE TYPE - ELECTRIC8123A3	RR SUSP TYPE - MULTI LINK-SPORTY5511B2	DR FRAME GARNISH - BLACK(GLOSSY)8225A2

ENGINE PACKAGE - VGT REGULAR ENG	0091A5	CENTER TRIM - ARTIFICIAL LEATHER	8233E1	TAIL GATE PANEL MATERIAL - STEEL	8172A1
FR COOLER - DUAL FULL AUTO A/CON	9761A6	IGNITION ILLUMINATED - BULB TYPE	8195A1	TRUNK LID PANEL MATERIAL - STEEL	8121A1
SPEAKER LOCATION FR DR - GENERAL	963CA1	FREQUENCY VIBRATION - AM9K/FM50K	9615A3	BODY CONTROL MODULE - BCM(ETACS)	9541A1
AIR BAG LABEL(PAS'S) - PICTOGRAM	569BE1	ROOF TRIM MATERIAL - CLOTH(STD)	8531A3	PASS"S SIDE - ELECTRIC HTD-CONV	8762C4
PRE TENSIONER - ELECTRICAL TYPE	888AA2	EU+AUSTRALIA TYPE - WIRING ONLY	2536A4	T/LID INSIDE HANDLE - HOOK TYPE	8125A2
ROOF - ROOF RACK - SILVER PAINT	8672A5	INSIDE HNDL OVER RIDE - ALL DR	8135A3	DR BELT LINE E/PIECE - NATURAL	8224A7
HAC (HILLSTART ASSIST CONTROL)	589HA1	HOOD OPENING DEVICE - GAS LIFT	8112A2	VOLUME KNOB TYPE - EUROPE TYPE	9616A1
HEAD REST - UP/DOWN & SLIDING	8821A5	AVERAGE FUEL CONSUMPTION(AFC)	965BA1	HEAD REST - UP/DOWN & SLIDING	8854A5
IMPACT SENS"G AUTO DR UNLOCKG	813BA1	VOICE RECOGNITION SYSTEM REMO	967FA1	TIRE PRESSURE LABEL - GERMANY	529AA3
FUEL TANK-CAPACITY - 70 LITER	3111D1	ONE TOUCH TRIPLE TURN SIGNAL	923DA1	LAMP TYPE - SEPARATED INSIDE	9245A2
RR P/TRAY MATERIAL - W/PAPER	8561A2	ELECTRIC CHROMIC MIRROR TYPE	8511C1	PADDLE SHIFTER - LEVER TYPE	967KA1
MID-RANGE SPEAKER(STANDARD)	9635A2	MULTIFUNCTION SW TYPE - LHD	9340A1	FR DR GLASS - SOLAR CONTROL	8241A3
AL WHEEL 7.5J * 18 - A TYPE	5291XK	IGN KEY REMOVG AT DR UNLOCK	813XA1	EXTERNAL CONTROL COMPRESSOR	979EA1
TRUNK LID TRIM - FULL COVER	8124A1	LICENCE PLATE - EUROPE TYPE	6921D1	ESS (EMERGENCY STOP SIGNAL)	5896A1
RR HEATING DUCTS - 2ND SEAT	9741A1	HOOD PANEL MATERIAL - STEEL	8111A1	CATALYTIC CONVERTER - D.P.F	2891F1
AUTO CRUISE CONTROL - SMART	9641A2	FR BLIND SPOT MONITOR"G SYS	965MA1	SMART KEY-TRUNK LID(T/GATE)	819KA1
DR AJAR - DR OPEN POSITION	94D0A2	RR QTR GLASS TYPE -PRIVACY	8791C1	LEVER FINISH"G - CR COAT"G	8262A2
ADJUSTER - HEIGHT ADJUSTER	8825A2	VANITY MIRROR - GLASS TYPE	852GA1	VANITY MIRROR - GLASS TYPE	8522A1
ADJUSTER - HEIGHT ADJUSTER	8857A2	SPEAKER LOCATION CENTER-FR	963EA1	AVERAGE VEHICLE SPEED(AVS)	965CA1
O/SIDE TEMPERATURE DISPLAY	965QA1	PASSENGER SIDE - DEPOWERED	5692A3	S/BELT ANCHOR - ADJUSTABLE	888KA2
CENTRAL T/GATE LOCK/UNLOCK	8177A1	REFRIGERATOR - ALTERNATIVE	9768A2	S/BELT ANCHOR - ADJUSTABLE	888RA2

LUGGAGE FLOOR RAIL SYSTEM	85B4A1	AT KNOB - LEATHER WRAPPED	4371B3	SPEED SENS"G AUTO DR LOCK	813AA1
MLD"G-S/SILL - BODY COLOR	8772B1	KEY TYPE - INSIDE CUTTING	8191A2	FINISH"G - HALF CR COAT"G	8261A3
CHILD SAFETY RR DR LOCK"G	8136A1	SUSPENSION SPEC - EUROPE	541BA2	B TYPE - BLACK+CR COAT"G	8631B4
TAIL GATE TYPE - LIFT UP	8171A1	WASHER FLUID WARN"G LAMP	94GOA1	ANTI-CORROSION TREATMENT	8648A1
DRL - DEDICATED LED TYPE	9213A4	STEER"G LOCK TYPE - ESCL	8198A3	DR MOOD LAMP - MOOD LAMP	823XA1
DISTANCE TO EMPTY(D.T.E)	965AA1	DLX - ARTIFICIAL LEATHER	8461B4	SINGLE BOOSTER - 11 INCH	5911A6
CUP HOLDER - FR(W/O ILL)	8462A1	CIGAR LIGHTER - W/ ILLUM	8445A2	ELECTRIC FOLD"G CONTROL	876MA1
ABS (ANTI LOCK BRK SYS)	5891A2	TYPE - INTERGRATED TYPE	9651A2	SPEEDOMETER TYPE - KMPH	94MDA1
DRIVER SIDE - DEPOWERED	5691A3	DELAY OUT INTERIOR LAMP	928KA1	INSTANT FUEL CONSUMPTIO	965EA1
INTERIOR LAMP - AUTOCUT	371FA1	INTEGRATED - CLEAR LENS	9231B1	FENDER MATERIAL - STEEL	6631A1
FR BRAKE - DISC-17 INCH	5811A6	MAP POCKET TYPE - FIXED	82B5A1	T/LID EMERGENCY RELEASE	812AA1
RR BRAKE - DISC-16 INCH	5812A9	SEAT BACK PNL(W/POCKET)	8836A3	LUMBAR SUPPORT - 4 WAY	8828A3
TX-INKEY TYPE - TX 2EA	8192C3	LEVELING DEVICE - AUTO	921BA2	TIE DOWN HOOK(LASHING)	8642A1
PASSENGER"S SIDE - ELR	8884D1	TIRE SOURCE - MICHELIN	5294B1	DR FRAME MLDG - BRIGHT	8221A2
TIRE MATERIAL - SILICA	5295A2	MUFFLER MATERIAL - SUS	2865A2	A/T POSITION INDICATOR	94C1A1
PEDAL TYPE - METAL PAD	3281A3	TRUNK LID(T/GATE) OPEN	94D7A1	EXTERNAL AMP - JBL AMP	963WA2
LUGGAGE SIDE - W/PAPER	8571C1	DUAL HORN - SHELL TYPE	9661B2	KEYLESS ENTRY-B/ALARM	819AA1
NOZZLE - SPRAY WASHER	9851A1	PARKG BRK CONTROL-EPB	5971A4	FUNCTION - AIR FILTER	9714A1
MATERIAL - CLOTH(STD)	8523A3	RR DR GLASS - PRIVACY	8245A5	SAPARATED-INSIDE LAMP	9246A1
DRIVER'S KNEE AIR BAG	5697A1	MATERIAL - CLOTH(STD)	8521A3	CURTAIN - MANUAL TYPE	823BA1
LED (DYNAMIC BENDING)	921KA2	SMART CRUISE CONTROL	94F3A2	BRAKE PAD - EUROPEAN	5813A2

SUS TYPE - LAMP TYPE	858RC2	H.M.S.L - T/GATE INR	8722A2	KEYLESS ENTRY-T/OPEN	819CA1
ISO FIX CHILD ANCHOR	892RA1	TEMPERATURE UNIT - C	94NOA1	DRIVER'S SIDE - ELR	888B1
PARK"G BRAKE WARN"G	9686A1	HOLDER - UPR ANCHOR	892DA1	PTC HEATER_INT TYPE	9713A2
N/PUNCH - FLAT TYPE	8421D1	VANITY MIRROR COVER	852BA1	ENGINE COVER - FULL	2921A4
TYPE - SLIDING TYPE	852EA2	VANITY MIRROR COVER	852HA1	TYPE - SLIDING TYPE	852LA2
KEY OPERATED WARN"G	9684A1	DIRECTION INDICATOR	94C6A1	POWER SEAT (I.M.S)	8849A1
SAFETY BARRIER NET	857NA1	BACK WARN"G CAMERA	9652A1	AUTO LIGHT CONTROL	9219A1
FR - W/ SUNGLASSES	9282A1	BULB TYPE - 2 BULB	928WA2	LCD ODO/TRIP METER	940EA1
SIDE REPEATER LAMP	876NA1	FLOOR - WALL PAPER	8573A2	COLOR - BODY COLOR	8652B1
MLD"G - BODY COLOR	8731B1	RR HEATED W/ TIMER	871BA1	MTG TYPE - BOLTING	6412A2
COLOR - BODY COLOR	8765A2	SEAT BELT REMINDER	8889A1	SEAT BELT REMINDER	888DA1
KICKDOWN MECHANISM	327AA1	SECURITY INDICATE	813MA1	HYDROPHOBIC GLASS	8242A1
RR - CONVENTIONAL	9222A1	LED POSITION TYPE	921LA1	BLADE TYPE - AERO	9819A2
VOICE RECOGNITION	965VA1	AUTO DEFOG SYSTEM	972MA1	FORMED TYPE - STD	8231B1
T/LID HINGE COVER	812EA1	LH/RH - BJ95+TJ95	4951B6	PAB ON/OFF SWITCH	569EA1
CONSOLE UPR COVER	84H4A1	3-SPOKE - LEATHER	5611B3	BATTERY UPR COVER	371AA1
MAP POCKET-RR DR	82A7A1	IGN KEY REMINDER	813DA1	ACTIVE ECO - S/W	94X9A1
COMPONENT- 2 DIN	9614B1	LUGGAGE NET HOOK	8578A1	HTR CONTROL KNOB	84FEA1
FR WIPER-2 SPEED	981AA1	ELAPSE TIME(E/T)	965DA1	MAP POCKET-FR DR	82A5A1
VIN LABEL - VIN	864EA1	BLUE TOOTH REMO	967EA1	WATER SEPARATER	94H2A1
RR POWER OUTLET	8464A1	CLUSTER IONIZER	9717A1	CTR UNDER COVER	8411A1

TOWING HOOK(FR)	864JA1	RR - WALL PAPER	8572A3	W/ WIPER DEICER	86A1A1
SMART KEY-FR DR	819HA1	DOUBLE RECLIN"G	885EA2	S/BELT REMINDER	898JA1
TOWING HOOK(RR)	864KA1	ROLLOVER SENSOR	569HA1	DOUBLE RECLIN"G	8824A2
TYPE - 2.5 MILE	8651B1	LENS TYPE - LED	8723A2	DOUBLE PIPE IHX	9763A1
AUTO STOP (ISG)	94X4A1	FLOOR MTG TYPE	3283A1	GLOW INDICATOR	94G5A1
BATTERY CHARGE	94D1A1	LUGGAGE SCREEN	857IA1	FR - BULB TYPE	9284A1
MIRROR FOLDING	819LA1	HOOD INSULATOR	811AA1	CONSOLE A/VENT	974AA1
B PILLAR - STD	858BA1	TYPE - DIGITAL	9451A1	D PILLAR - STD	858EA1
C PILLAR - STD	858CA1	A PILLAR - STD	858AA1	AMBIENT SENSOR	971BA1
ENG OIL LEVEL	94H8A1	TICKET HOLDER	852AA1	O/SIDE HANDLE	812BA1
BATTERY SAVER	371CA1	MIST FUNCTION	9817A1	H/LAMP WASHER	9214A1
CURTAIN A/BAG	5695A1	FR - PORTABLE	8441A5	REMOTE FOLD"G	89E4A1
FOG LAMP (FR)	94C4A1	GEAR POSITION	94C2A1	CTR AIR VENT	84FDA1
LOAD LIMITER	889MA1	CHECK ENGINE	94D9A1	POWER OUTLET	857AA1
LOAD LIMITER	888EA1	OIL PRESSURE	94C7A1	PARK"G BRAKE	94C9A1
DRINK HOLDER	89C1A1	LUGGAGE LAMP	9287A1	RR FOG LAMP	94D5A1
WATER TEMP.	940DA1	SPEEDOMETER	9402A1	W/ MAP LAMP	9297A1
AUDIO REMO.	967AA1	SET CONTROL	94F4A1	IMMOBILIZER	94H6A1
RAIN SENSOR	9815A1	ILLUMINATED	852DA1	IMMOBILIZER	9542A1
ILLUMINATED	852KA1	POWER SEAT	8827A1	TAIL LIGHT	94W1A1
AUDIO KNOB	84FCA1	TACHOMETER	940BA1	SIDE - ELR	8981A4

HIGH GRADE	6501A1	HIGH BEAM	94D2A1	RR - 1 EA	853JA1
BRAKE OIL	94C8A1	FR - LAMP	928HA1	W/ HEATED	561AA1
CTR - ELR	8982A4	ACC REMO.	967BA1	SEAT BELT	968JA1
W/ DAMPER	8452A2	FR - 1 EA	8532A1	SEAT BELT	94E3A1
RR - 2 EA	853AA2	E.S.P OFF	94J0A1	LED TYPE	9241A3
LOW FUEL	94D4A1	RHEOSTAT	9491A1	LOW BEAM	94D3A1
ANTI-FOG	921FA1	W/ ILLUM	845BA1	L.K.A.S	9579A2
USB+AUX	9618A1	SLIDING	885DA1	W/O BOX	89B1A1
SLIDING	8823A1	W/ LOCK	8451A2	H-MATIC	4509A1
FOB KEY	819GA1	ESCORT	921JA1	I.M.S	876BA2
E.S.P	94H9A1	A/BAG	94E6A1	A.B.S	94E5A1
MDPS	94H7A1	FUEL	940CA1	Opis --	8778B3
Opis --	965YA1	Opis --	9221F2	Opis --	957EA1
Opis --	9211G2	Opis --	876KA1	Opis --	857RA2
Opis --	915LA1	Opis --	963VA9	Opis --	9636A2
Opis --	87A2A1	Opis --	9572A2	Opis --	961NFD
Opis --	957LA3	Opis --	957AA2	Opis --	957HA1
Opis --	WT 3	Opis --	8918B1	Opis --	8122A4
Opis --	824RE2	Opis --	898AA1	Opis --	892XA1
Opis --	8919B1	Opis --	8917B1	Opis --	8912H1
Opis --	885CA3	Opis --	882BA3	Opis --	8665A2

Opis --863AF3	Opis --8471C1	Opis --824PE2
Opis --89B3A1	Opis --824GE2	Opis --823IA3
Opis --819DA1	Opis --7932A3	Opis --7931A3
Opis --5711B2	Opis --5512A7	Opis --5412A7
Opis --2841B8	Opis --0101B6	Opis --898DA1
Opis --915AA1	Opis --589DA1	Opis --9627A1
Opis --589CA1	Opis --589BA1	Opis --5894A2
Opis --5555A1	Opis --5293JF	Opis --3734A3
Opis --3731B4	Opis --9767A3	Opis --967HA1
Opis --965TA1	Opis --961KA1	Opis --915BA1
Opis --9611ZD	Opis --9552E1	Opis --9549A1
Opis --94XGA1	Opis --928FB5	Opis --915NA1
Opis --915MA1	Opis --915EA1	Opis --915DA1
Opis --915CA1	Opis --967JA1	

ARCHIWALNE ZDJĘCIA POJAZDU

Liczba zdjęć --

Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez AUTODNA Sp. z o.o. o tym fakcie. AUTODNA Sp. z o.o. nie ponosi odpowiedzialności za treść danych zawartych w Raportach. Treść taka może być niepełna lub niezgodna ze stanem rzeczywistym.

Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody AUTODNA Sp. z o.o.

AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

AUTODNA Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez AUTODNA Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.

autoDNA


Raport Historii Pojazdu autoDNA



Zeskanuj mnie!


KNAGU815GH5160656

Kia OPTIMA



Jak skanować QR kod

Uruchom aparat w swoim telefonie i skieruj obiektyw telefonu na kod QR. Telefon automatycznie zeskanuje QR kod. Alternatywnie, uruchom aplikację do skanowania QR i postępuj analogicznie.



Jak nakleić na szybę

Naklej na boczną szybę samochodu, po prawej lub lewej stronie. Nie rekomendujemy naklejania na przednią szybę, która ustawiona jest pod kątem przez co trudniej będzie zeskanować QR kod.



Jak umieścić zdjęcie w ogłoszeniu

Dodaj QR kod jako kolejne zdjęcie do swojego ogłoszenia. Popularne serwisy umożliwiają dodawanie zdjęcia w rozmiarze do 5 MB o rozdzielczości 1080 x 720 px. Plik, który otrzymałeś od nas wraz z zamówionym raportem spełnia te wymagania. Po prostu dodaj zdjęcie do galerii sprzedawanego pojazdu.