



Raport Historii Pojazdu autoDNA

Raport zawiera dostępne informacje na dzień: 2022-09-26 13:26:08 UTC +0200

Wersja językowa: PL

b84fcc76-5ae1efe0-f0171ae3-03a09de0-e8ba4d25



Kia OPTIMA
KNAGU415AJ5256196

Wiek pojazdu

Wg daty produkcji / roku modelowego

4

LAT(A)

8

MIES.

Data produkcji / Rok modelowy 2018

Wg pierwszej rejestracji pojazdu

3

LAT(A)

9

MIES.

Data pierwszej rejestracji 2018-12-10

7 1 3 9 7 km

Uwaga: Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

CENTRUM POWIADOMIEŃ

Bazy Skradzionych Pojazdów



Przeszukane bazy 11/11

Akcje serwisowe



Nie odnotowano

Informacje o pojeździe



Liczba wpisów 17

Dziennik użytkowania



Liczba wpisów 10

Historia cenowa



Nie odnotowano

Odczyty drogomierza



Liczba wpisów 5

Historia uszkodzeń

 Liczba wpisów 3

Wyposażenie

 Liczba wpisów 367

Archiwalne zdjęcia

 Liczba wpisów 0

Poprawność VIN

 Niedostępne

INFORMACJE O POJEŹDZIE

Producent
KIA**Typ paliwa**
DIESEL**Rok modelowy**
2018**Data produkcji**
2018**Skrzynia biegów**
6-BIEGOWA**Średnie spalanie [l/100km]**
6.51**Model**
OPTIMA**Pojemność silnika [cm3]**
1700**Kod koloru lakieru**
B4U**Silnik**
1.7L DOHC TCI**Napęd**
2WD**Rynek przeznaczenia**
C27, POLAND**Rodzaj nadwozia**
SEDAN / LIMUZyna**Kraj producenta**
KOREA POŁUDNIOWA**Kod koloru wnętrza**
WK**Typ skrzyni biegów**
MANUALNA**Kod modelu**
KEURPD416

AKCJE SERWISOWE



Nie odnotowano

BAZA SKRADZIONYCH POJAZDÓW

Przeszukane bazy 11

Odnotowano 0



Czechy

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano



Rumunia


Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

 Litwa Ewidencja pojazdów skradzionych - Policja ✓ Nie odnotowano	 Słowenia Ewidencja pojazdów skradzionych - Policja ✓ Nie odnotowano
 Holandia Ewidencja pojazdów skradzionych - Repozytoria Criminail oraz Stowarzyszenie Ubezpieczycieli ✓ Nie odnotowano	 Kanada Ewidencja pojazdów skradzionych - Policja ✓ Nie odnotowano
 Słowacja Ewidencja pojazdów skradzionych - Policja ✓ Nie odnotowano	 Szwecja Ewidencja pojazdów skradzionych - Stowarzyszenie Ubezpieczycieli ✓ Nie odnotowano
 Norwegia Ewidencja pojazdów skradzionych - Ettersokt ✓ Nie odnotowano	 Kaynine Ewidencja przedmiotów skradzionych - Kaynine(Niemcy) ✓ Nie odnotowano
 Baza int. Ewidencja pojazdów skradzionych - Niezależne źródła internetowe ✓ Nie odnotowano	

HISTORIA POJAZDU



Kwota **2000 - 2500 PLN**

Rezultat



USZKODZENIE NADWOZIA

Grupa części

- Elementy karoserii zewnętrznej

Kraj **Polska**



Strefa uszkodzenia
- Tył

2021

10.12.2021

Wykonano okresowe badanie techniczne

Stan drogomierza
55 521 km

Wynik **Pozytywny**

Termin badania technicznego **2023-12-10**

Kraj **Polska**

10.12.2021

Ubezpieczenie pojazdu

Polisa ważna do **2022-12-09**

Kraj **Polska**

16.09.2021

Ubezpieczenie pojazdu

Polisa ważna do **2022-09-15**

Kraj **Polska**

2020

10.12.2020

Ubezpieczenie pojazdu

Polisa ważna do **2021-12-09**

Kraj **Polska**

11.2020

Zgłoszono odczyt drogomierza

Stan drogomierza
38 255 km

11.2020

Odnotowano szkodę na pojeździe

Kwota **1500 - 2000 PLN**

Rezultat



USZKODZENIE NADWOZIA



Strefa uszkodzenia
- Prawa strona

Kraj **Polska**

16.09.2020

Ubezpieczenie pojazdu

Polisa ważna do **2021-09-15**

Kraj **Polska**

2019

10.12.2019

Ubezpieczenie pojazdu

Polisa ważna do **2020-12-09**

Kraj **Polska**

01.2019

Zgłoszono odczyt drogomierza

Stan drogomierza
2 907 km

01.2019

Odnotowano szkodę na pojeździe

Kwota **4000 - 4500 PLN**

Rezultat



USZKODZENIE PODWOZIA



USZKODZENIE NADWOZIA

Grupa części

- Układ zawieszenia
- Elementy karoserii zewnętrznej
- Szyby

Kraj **Polska**



Strefa uszkodzenia
- Prawa strona
- Tył
- Lewy tył

2018

13.12.2018

Rozpoczęcie okresu gwarancyjnego

10.12.2018

Pojazd zarejestrowany**Homologowany fabrycznie**Termin badania technicznego **2021-12-09**Kraj **Polska**

10.12.2018

Pierwsza rejestracja pojazdu

30.10.2018

Zgłoszono odczyt drogomierzaStan drogomierza
5 km

30.10.2018

Serwis pojazdu

12.03.2018

Pojazd wyprodukowany

DZIENNIK SPRAWDZEŃ

Data i czas	Rodzaj usługi	IP	Lokalizacja
--	--	--	--

WYPOSAŻENIE

PROJECTION - LOW BEAM-A TYPE (MFR STATIC) 9211F4	DR SIDE W/STRIP - RUBBER(SILICON COAT'G) 8212A1	BACK LITE GLASS TYPE -TINTED(W/SOLAR CNT) 8712B3
RETRACTOR PRETENSIONER - ELECTRICAL TYPE 8885A2	CLUSTER TYPE - SUPER VISION 4.2" TFT LCD 9401D5	STEER"G COLUMN-MANUAL TILT & TELESCOPIC 5631A4
SEAT WARMER (HEATER) - 3-STEPS (BUTTON) 8873B4	SEAT WARMER (HEATER) - 3-STEPS (BUTTON) 8838B4	UPR TRIM FINISH'G - TPO (THERMO PLASTIC) 8232A8
DR BELT LINE MLD'G - BLACK-SUS+PVC TYPE 8223A2	BODY SIDE W/STRIP-RUBBER(SILICON COAT'G) 8211A1	RR QTR GLASS TYPE -TINTED(W/SOLAR CNTL) 8791B2
CENTRAL DR LOCK/UNLOCK-DR"S & PA"S CTRL 8131A2	P/WINDOW RR DR - AUTO UP/DOWN & SAFETY 824CA6	TIRE PRESSURE MONITORG SYS - HIGH LINE 9574A1
LWR TRIM (MAIN TRIM)PLASTIC(NO COVERG) 82A8A1	BATTER CAPACITY AGM TYPE - 64AH (5HR) 3711C3	ARM REST COVER"G - ARTIFICIAL LEATHER 8236A3

PASS'S SIDE - ELECTRIC HTD-CONV(WIDE)	8762C5	LUMBAR SUPPORT - ELECT LUMBER SUPPORT	8828A2	SIDE AIR BAG-FR - FR(THORAX & PELVIS)	5693A3
SENSOR-AIR FLOWER - NON SPEED DENSITY	3921A1	P/WINDOW PA'S - AUTO UP/DOWN & SAFETY	824BA6	O.B.D(ON-BOARD DIAGNOSTICS) - E.O.B.D	2845A2
P/WINDOW DR"S - AUTO UP/DOWN & SAFETY	824AA6	W/ STORAGE BOX ARM REST - STD(1 DIN)	846BA1	FUEL FILLER DR FINISH'G - BODY COLOR	8153A1
6:4 SPLIT BACK FOLD"G - CUSHION+BACK	8912D4	W/S GLASS TYPE-TINTED (W/ S/B,SOLAR)	8611B3	POCKET LIGHTING - FRT DOOR - W/ILLUM	826DA1
MUFFLER MAIN ASSY - SINGLE-CR COAT"G	2861A2	BUTTON START - BUTTON W/ ILLUMINATED	8196A2	SEAT BACK - SEAT BACK PNL(W/POCKET)	886BA3
AUTO LIGHT CONTROL SYSTEM - 1 STAGE	9511A1	FR SUSP TYPE - MACPH. W/COIL SPRING	5411A1	CARRIER MATERIAL - PLASTIC(HYBRID)	6411A1
FUEL FILLER DR REL TYPE - ELECTRIC	8152A4	DRIVER"S - ELECTRIC HTD-CONV(WIDE)	8763C7	ESC (ELECTRONIC STABILITY CONTROL)	5894A1
SPEAKER LOCATION RR DR LOW-GENERAL	963ZA1	VSM (VEHICLE STABILITY MANAGEMENT)	589GA1	AUTO CRUISE CONTROL - CONVENTIONAL	9641A1
TRUNK LID RELEASE TYPE - ELECTRIC	8123A3	FUEL FILLER DR MATERIAL - PLASTIC	8151A2	A/CLOTH(CLOTH+ARTIFICIAL LEATHER)	8811B4
TPMS (TIRE PRESSURE MONITORG SYS)	94K3A1	FR WIPER - INTERMITTENT(VARIABLE)	9811A2	FREQUENCY VIBRATION - AM9K/FM50K	9615A3
CENTER TRIM - ARTIFICIAL LEATHER	8233E1	IGNITION ILLUMINATED - BULB TYPE	8195A1	RR SUSP TYPE - MULTI LINK-SPORTY	5511B2
ENGINE PACKAGE - VGT REGULAR ENG	0091A5	SPEAKER LOCATION FR DR - GENERAL	963CA1	FR COOLER - DUAL FULL AUTO A/CON	9761A6
TRUNK LID PANEL MATERIAL - STEEL	8121A1	BODY CONTROL MODULE - BCM(ETACS)	9541A1	AIR BAG LABEL(PAS'S) - PICTOGRAM	569BE1
T/LID INSIDE HANDLE - HOOK TYPE	8125A2	PRE TENSIONER - ELECTRICAL TYPE	888AA2	ROOF TRIM MATERIAL - CLOTH(STD)	8531A3
TEMPORARY - STEEL WHEEL & TIRE	5297C1	HOOD OPENING DEVICE - GAS LIFT	8112A2	HAC (HILLSTART ASSIST CONTROL)	589HA1
DR BELT LINE E/PIECE - NATURAL	8224A7	VOLUME KNOB TYPE - EUROPE TYPE	9616A1	INSIDE HNDL OVER RIDE - ALL DR	8135A3
HEAD REST - UP/DOWN & SLIDING	8821A5	FUEL TANK-CAPACITY - 70 LITER	3111D1	IMPACT SENS'G AUTO DR UNLOCKG	813BA1
VOICE RECOGNITION SYSTEM REMO	967FA1	HEAD REST - UP/DOWN & SLIDING	8854A5	AVERAGE FUEL CONSUMPTION(AFC)	965BA1
RR P/TRAY MATERIAL - W/PAPER	8561A2	ELECTRIC CHROMIC MIRROR TYPE	8511C1	TIRE PRESSURE LABEL - EUROPE	529AB1
SPEED LIMITER - DISPLAY TYPE	94X5A1	ONE TOUCH TRIPLE TURN SIGNAL	923DA1	LAMP TYPE - SEPARATED INSIDE	9245A2
RR HEATING DUCTS - 2ND SEAT	9741A1	RR DR GLASS - SOLAR CONTROL	8245A3	FR DR GLASS - SOLAR CONTROL	8241A3
MID-RANGE SPEAKER(STANDARD)	9635A2	AL WHEEL 7.5J * 17 - A TYPE	5291XF	MULTIFUNCTION SW TYPE - LHD	9340A1

CATALYTIC CONVERTER - D.P.F	2891F1	ESS (EMERGENCY STOP SIGNAL)	5896A1	LICENCE PLATE - EUROPE TYPE	6921D1
TRUNK LID TRIM - FULL COVER	8124A1	SMART KEY-TRUNK LID(T/GATE)	819KA1	IGN KEY REMOVG AT DR UNLOCK	813XA1
HOOD PANEL MATERIAL - STEEL	8111A1	EXTERNAL CONTROL COMPRESSOR	979EA1	MLD"G-S/SILL TYPE - A TYPE	8778B1
VANITY MIRROR - GLASS TYPE	8522A1	ADJUSTER - HEIGHT ADJUSTER	8857A2	VANITY MIRROR - GLASS TYPE	852GA1
S/BELT ANCHOR - ADJUSTABLE	888RA2	AVERAGE VEHICLE SPEED(AVS)	965CA1	LEVER FINISH"G - CR COAT"G	8262A2
O/SIDE TEMPERATURE DISPLAY	965QA1	DR AJAR - DR OPEN POSITION	94D0A2	REFRIGERATOR - ALTERNATIVE	9768A2
S/BELT ANCHOR - ADJUSTABLE	888KA2	ADJUSTER - HEIGHT ADJUSTER	8825A2	PASSENGER SIDE - DEPOWERED	5692A3
MT KNOB - LEATHER WRAPPED	4371A3	FINISH"G - HALF CR COAT"G	8261A3	TIRE SOURCE - CONTINENTAL	5294B9
MLD"G-S/SILL - BODY COLOR	8772B1	KEY TYPE - INSIDE CUTTING	8191A2	SPEED SENS"G AUTO DR LOCK	813AA1
CHILD SAFETY RR DR LOCK"G	8136A1	SINGLE BOOSTER - 11 INCH	5911A6	WASHER FLUID WARN"G LAMP	94G0A1
CIGAR LIGHTER - W/ ILLUM	8445A2	STEER"G LOCK TYPE - ESCL	8198A3	DISTANCE TO EMPTY(D.T.E)	965AA1
SUSPENSION SPEC - EUROPE	541BA2	DLX - ARTIFICIAL LEATHER	8461B4	CUP HOLDER - FR(W/O ILL)	8462A1
B TYPE - BLACK+CR COAT"G	8631B4	ANTI-CORROSION TREATMENT	8648A1	DRL - DEDICATED LED TYPE	9213A4
DRIVER SIDE - DEPOWERED	5691A3	INSTANT FUEL CONSUMPTIO	965EA1	FENDER MATERIAL - STEEL	6631A1
SPEEDOMETER TYPE - KMPH	94MOA1	INTEGRATED - CLEAR LENS	9231B1	ELECTRIC FOLD"G CONTROL	876MA1
RR BRAKE - DISC-15 INCH	5812A8	TYPE - INTERGRATED TYPE	9651A2	MAP POCKET TYPE - FIXED	82B5A1
FR BRAKE - DISC-16 INCH	5811A5	SEAT BACK PNL(W/POCKET)	8836A3	INTERIOR LAMP - AUTOCUT	371FA1
DELAY OUT INTERIOR LAMP	928KA1	T/LID EMERGENCY RELEASE	812AA1	ABS (ANTI LOCK BRK SYS)	5891A2
LEVELING DEVICE - AUTO	921BA2	PASSENGER"S SIDE - ELR	8884D1	TX-INKEY TYPE - TX 2EA	8192C3
TIRE MATERIAL - SILICA	5295A2	SPEED LIMITER - A TYPE	964LA1	MUFFLER MATERIAL - SUS	2865A2
TIE DOWN HOOK(LASHING)	8642A1	LUGGAGE SIDE - W/PAPER	8571C1	TRUNK LID(T/GATE) OPEN	94D7A1

DUAL HORN - SHELL TYPE	9661B2	DR FRAME MLDG - BRIGHT	8221A2	SAPARATED-INSIDE LAMP	9246A1
DRIVER'S KNEE AIR BAG	5697A1	GLASS ANTENNA - RADIO	9621E1	NOZZLE - SPRAY WASHER	9851A1
215 TIRE - 215/55 R17	5293GC	FUNCTION - AIR FILTER	9714A1	MATERIAL - CLOTH(STD)	8521A3
KEYLESS ENTRY-B/ALARM	819AA1	MATERIAL - CLOTH(STD)	8523A3	PARKG BRK CONTROL-EPB	5971A4
ISO FIX CHILD ANCHOR	892RA1	KEYLESS ENTRY-T/OPEN	819CA1	TEMPERATURE UNIT - C	94N0A1
BRAKE PAD - EUROPEAN	5813A2	PARK"G ASSIST SYSTEM	9571A2	TRIM - RR TRANSVERSE	857RA1
TYPE - SLIDING TYPE	852EA2	PARK"G BRAKE WARN"G	9686A1	ENGINE COVER - FULL	2921A4
PTC HEATER_INT TYPE	9713A2	HOLDER - UPR ANCHOR	892DA1	DRIVER"S SIDE - ELR	8881B1
VANITY MIRROR COVER	852HA1	N/PUNCH - FLAT TYPE	8421D1	TYPE - SLIDING TYPE	852LA2
VANITY MIRROR COVER	852BA1	DIRECTION INDICATOR	94C6A1	H.M.S.L - RR P/TRAY	8722A3
KEY OPERATED WARN"G	9684A1	M/T SHIFT INDICATOR	94X6A1	SEAT BELT REMINDER	8889A1
LCD ODO/TRIP METER	940EA1	BACK WARN"G CAMERA	9652A1	BULB TYPE - 2 BULB	928WA2
SEAT BELT REMINDER	888DA1	AUTO LIGHT CONTROL	9219A1	COLOR - BODY COLOR	8765A2
MTG TYPE - BOLTING	6412A2	COLOR - BODY COLOR	8652B1	RR HEATED W/ TIMER	871BA1
KICKDOWN MECHANISM	327AA1	MLD"G - BODY COLOR	8731B1	FLOOR - WALL PAPER	8573A2
SIDE REPEATER LAMP	876NA1	FR - W/ SUNGLASSES	9282A1	BATTERY UPR COVER	371AA1
LH/RH - BJ95+TJ95	4951B6	VOICE RECOGNITION	965VA1	3-SPOKE - LEATHER	5611B3
RR - CONVENTIONAL	9222A1	BLADE TYPE - AERO	9819A2	FORMED TYPE - STD	8231B1
SECURITY INDICATE	813MA1	LED POSITION TYPE	921LA1	AUTO DEFOG SYSTEM	972MA1
HYDROPHOBIC GLASS	8242A1	PAB ON/OFF SWITCH	569EA1	T/LID HINGE COVER	812EA1
CONSOLE UPR COVER	84H4A1	COMPONENT- 2 DIN	9614B1	IGN KEY REMINDER	813DA1

FR WIPER-2 SPEED	981AA1	HTR CONTROL KNOB	84FEA1	MAP POCKET-FR DR	82A5A1
ELAPSE TIME(E/T)	965DA1	MAP POCKET-RR DR	82A7A1	LUGGAGE NET HOOK	8578A1
DOUBLE PIPE IHX	9763A1	RR - WALL PAPER	8572A3	CTR UNDER COVER	8411A1
VIN LABEL - VIN	864EA1	TOWING HOOK(FR)	864JA1	TOWING HOOK(RR)	864KA1
TYPE - 2.5 MILE	8651B1	W/ WIPER DEICER	86A1A1	ROLLOVER SENSOR	569HA1
SMART KEY-FR DR	819HA1	LENS TYPE - LED	8723A2	DOUBLE RECLIN"G	8824A2
RR POWER OUTLET	8464A1	DOUBLE RECLIN"G	885EA2	S/BELT REMINDER	898JA1
BLUE TOOTH REMO	967EA1	WATER SEPARATER	94H2A1	CONSOLE A/VENT	974AA1
BATTERY CHARGE	94D1A1	GLOW INDICATOR	94G5A1	CRUISE CONTROL	94F3A1
TYPE - DIGITAL	9451A1	AMBIENT SENSOR	971BA1	A PILLAR - STD	858AA1
DR SCUFF - STD	858RA1	MIRROR FOLDING	819LA1	B PILLAR - STD	858BA1
HOOD INSULATOR	811AA1	C PILLAR - STD	858CA1	FLOOR MTG TYPE	3283A1
O/SIDE HANDLE	812BA1	BATTERY SAVER	371CA1	GEAR POSITION	94C2A1
FOG LAMP (FR)	94G4A1	TICKET HOLDER	852AA1	ENG OIL LEVEL	94HB8A1
FR - PORTABLE	844JA5	H/LAMP WASHER	9214A1	MIST FUNCTION	9817A1
CURTAIN A/BAG	5695A1	CHECK ENGINE	94D9A1	NON LED TYPE	9241A2
PARK"G BRAKE	94C9A1	OIL PRESSURE	94C7A1	CTR AIR VENT	84FDA1
MUD GUARD-FR	8681A1	MUD GUARD-RR	8682A1	LOAD LIMITER	888EA1
LOAD LIMITER	889MA1	DRINK HOLDER	89C1A1	LUGGAGE LAMP	9287A1
IMMOBILIZER	94H6A1	RAIN SENSOR	9815A1	CLUTCH LOCK	4501A1
ILLUMINATED	852DA1	ILLUMINATED	852KA1	AUDIO REMO.	967AA1

IMMOBILIZER	9542A1	LUGGAGE NET	8579A1	W/ MAP LAMP	9297A1
WATER TEMP.	940DA1	SPEEDOMETER	9402A1	RR FOG LAMP	94D5A1
SET CONTROL	94F4A1	SIDE - ELR	8981A4	TAIL LIGHT	94W1A1
HIGH GRADE	6501A1	AUDIO KNOB	84FCA1	TACHOMETER	940BA1
RR - 2 EA	853AA2	ACC REMO.	967BA1	FR - 1 EA	8532A1
SEAT BELT	9681A1	BRAKE OIL	94C8A1	RR - 1 EA	853JA1
CTR - ELR	8982A4	SEAT BELT	94E3A1	CLUTCH SW	4502A4
W/ DAMPER	8452A2	W/ HEATED	561AA1	E.S.P OFF	94J0A1
HIGH BEAM	94D2A1	FR - LAMP	928HA1	LOW FUEL	94D4A1
LOW BEAM	94D3A1	ANTI-FOG	921FA1	RHEOSTAT	9491A1
W/ ILLUM	845BA1	W/ LOCK	8451A2	SLIDING	885DA1
L.K.A.S	9579A2	USB+AUX	9618A1	SLIDING	8823A1
FOB KEY	819GA1	W/O BOX	89B1A1	ESCORT	921JA1
E.S.P	94H9A1	A.B.S	94E5A1	A/BAG	94E6A1
MDPS	94H7A1	FUEL	940CA1	Opis --	8122A4
Opis --	2841B8	Opis --	9216C3	Opis --	915LA1
Opis --	9627A1	Opis --	957LA3	Opis --	961NF7
Opis --	9221F2	Opis --	9552E1	Opis --	9611ZD
Opis --	0101B7	Opis --	824RE2	Opis --	3731A3
Opis --	882BA3	Opis --	8919B1	Opis --	8918B1
Opis --	8917B1	Opis --	7931A3	Opis --	7932A3

Opis --885CA3	Opis --8665A2	Opis --898AA1
Opis --863AF3	Opis --819DA1	Opis --8225A3
Opis --823IA3	Opis --8471C1	Opis --824GE2
Opis --824PE2	Opis --892XA1	Opis --898DA1
Opis --9767A3	Opis --928FB5	Opis --967LA2
Opis --967HA1	Opis --5412A7	Opis --5512A7
Opis --961KA1	Opis --9549A1	Opis --5711B2
Opis --915PA1	Opis --89B3A1	Opis --915NA1
Opis --915MA1	Opis --915EA1	Opis --915DA1
Opis --915CA1	Opis --915BA1	Opis --915AA1
Opis --WT 2		

ARCHIWALNE ZDJĘCIA POJAZDU

Liczba zdjęć --

Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez AUTODNA Sp. z o.o. o tym fakcie. AUTODNA Sp. z o.o. nie ponosi odpowiedzialności za treść danych zawartych w Raportach. Treść taka może być niepełna lub niezgodna ze stanem rzeczywistym.

Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego. Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody AUTODNA Sp. z o.o.

AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

AUTODNA Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez AUTODNA Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.

autoDNA


Raport Historii Pojazdu autoDNA



Zeskanuj mnie!


KNAGU415AJ5256196

Kia OPTIMA



Jak skanować QR kod

Uruchom aparat w swoim telefonie i skieruj obiektyw telefonu na kod QR. Telefon automatycznie zeskanuje QR kod. Alternatywnie, uruchom aplikację do skanowania QR i postępuj analogicznie.



Jak nakleić na szybę

Naklej na boczną szybę samochodu, po prawej lub lewej stronie. Nie rekomendujemy naklejania na przednią szybę, która ustawiona jest pod kątem przez co trudniej będzie zeskanować QR kod.



Jak umieścić zdjęcie w ogłoszeniu

Dodaj QR kod jako kolejne zdjęcie do swojego ogłoszenia. Popularne serwisy umożliwiają dodawanie zdjęcia w rozmiarze do 5 MB o rozdzielczości 1080 x 720 px. Plik, który otrzymałeś od nas wraz z zamówionym raportem spełnia te wymagania. Po prostu dodaj zdjęcie do galerii sprzedawanego pojazdu.