



Raport Historii Pojazdu autoDNA

Raport zawiera dostępne informacje na dzień: 2022-11-04 14:13:51 UTC +0100

Wersja językowa: PL

625f71fd-50ef311c-5e511df0-b3057210-4faee220



Kia OPTIMA
KNAGU819GL5387986

Wiek pojazdu

Wg daty produkcji / roku modelowego

3

LAT(A)

10

MIES.

Data produkcji / Rok modelowy 2019

Wg pierwszej rejestracji pojazdu

2

LAT(A)

10

MIES.

Data pierwszej rejestracji 2019-12-11

4 2 2 8 3 km

Uwaga: Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

CENTRUM POWIADOMIEŃ

Bazy Skradzionych Pojazdów



Przeszukane bazy 12/12

Akcje serwisowe



Nie odnotowano

Informacje o pojeździe



Liczba wpisów 16

Dziennik użytkowania



Liczba wpisów 13

Historia cenowa



Liczba wpisów 3

Odczyty drogomierza



Liczba wpisów 7

Historia uszkodzeń

 Liczba wpisów 2

Wyposażenie

 Liczba wpisów 386

Archiwalne zdjęcia

 Liczba wpisów 64

Poprawność VIN

 Niedostępne

INFORMACJE O POJEŹDZIE

Producent
KIA**Typ paliwa**
DIESEL**Rok modelowy**
2019**Data produkcji**
2019**Napęd**
2WD**Średnie spalanie [l/100km]**
6.50**Model**
OPTIMA**Pojemność silnika [cm3]**
1600**Kod koloru lakieru**
4SS**Silnik**
1.6L DOHC TCI**Kod modelu**
KEURPD418**Rodzaj nadwozia**
KOMBI**Kraj producenta**
KOREA POŁUDNIOWA**Kod koloru wnętrza**
WK**Skrzynia biegów**
7-BIEGOWA**Rynek przeznaczenia**
EUROPE, POLAND

AKCJE SERWISOWE

 Nie odnotowano

BAZA SKRADZIONYCH POJAZDÓW

Przeszukane bazy 12

Odnnotowano 0

 **Włochy**

Ewidencja pojazdów skradzionych - Policja


 Nie odnotowano **Czechy**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano

 Rumunia Ewidencja pojazdów skradzionych - Policja  Nie odnotowano	 Litwa Ewidencja pojazdów skradzionych - Policja  Nie odnotowano
 Słowenia Ewidencja pojazdów skradzionych - Policja  Nie odnotowano	 Holandia Ewidencja pojazdów skradzionych - Repozytoria Criminail oraz Stowarzyszenie Ubezpieczycieli  Nie odnotowano
 Kanada Ewidencja pojazdów skradzionych - Policja  Nie odnotowano	 Słowacja Ewidencja pojazdów skradzionych - Policja  Nie odnotowano
 Szwecja Ewidencja pojazdów skradzionych - Stowarzyszenie Ubezpieczycieli  Nie odnotowano	 Norwegia Ewidencja pojazdów skradzionych - Ettersokt  Nie odnotowano
 Kaynine Ewidencja przedmiotów skradzionych - Kaynine(Niemcy)  Nie odnotowano	 Baza int. Ewidencja pojazdów skradzionych - Niezależne źródła internetowe  Nie odnotowano

HISTORIA POJAZDU



24.06.2022

Zgłoszono odczyt drogomierza

Stan drogomierza
87 216 km

21.03.2022

Odnotowano cenę / wartość

104 900 PLN brutto

21.03.2022

Zgłoszono odczyt drogomierza

Stan drogomierza
87 216 km

31.01.2022

Ubezpieczenie pojazdu

Polisa ważna do 2023-01-30

Kraj Polska

2021

11.12.2021

Ubezpieczenie pojazdu

Polisa ważna do 2022-12-10

Kraj Polska

04.12.2021

Przeprowadzenie kontroli drogowej pojazdu

Wartość drogomierza nieczytelna lub niekompletna

Kraj Polska

12.2021

Zgłoszono odczyt drogomierza

Stan drogomierza
80 000 km

12.2021

Odnotowano szkodę na pojeździe

Kwota > **50000 PLN**

Rodzaj uszkodzenia

**PRZEDNIA SZYBA**

Rezultat

**USZKODZENIE SZYB****USZKODZENIE WNĘTRZA****USZKODZENIE PODWOZIA****USZKODZENIE NADWOZIA**

Grupa części

- Układ bezpieczeństwa biernego
- Elementy karoserii zewnętrznej
- Elementy konstrukcyjne nadwozia
- Oświetlenie zewnętrzne
- Szyby
- Tapicerka
- Osprzęt silnika

Kraj **Polska**

Strefa uszkodzenia

- Przód
- Prawy przód
- Lewy przód
- Lewa strona
- Prawa strona
- Tył

30.04.2021**Serwis pojazdu****30.04.2021****Zgłoszono odczyt drogomierza**Stan drogomierza
58 801 km**02.04.2021****Serwis pojazdu****02.04.2021****Zgłoszono odczyt drogomierza**Stan drogomierza
54 796 km**2020****11.12.2020****Ubezpieczenie pojazdu**Polisa ważna do **2021-12-10**Kraj **Polska****06.2020****Odnotowano szkodę na pojeździe**

Kwota **3000 - 3500 PLN**

Rezultat



USZKODZENIE PODWOZIA



USZKODZENIE NADWOZIA

Grupa części

- Układ zawieszenia

Kraj **Polska**



Strefa uszkodzenia

- Lewy tył

03.01.2020

Przeprowadzenie kontroli drogowej pojazdu

Stan drogomierza
15 048 km

Kraj **Polska**

2019

17.12.2019

Rozpoczęcie okresu gwarancyjnego

16.12.2019

Serwis pojazdu

16.12.2019

Zgłoszono odczyt drogomierza

Stan drogomierza
5 km

11.12.2019

Ubezpieczenie pojazdu

Polisa ważna do **2020-12-10**

Kraj **Polska**

11.12.2019

Pojazd zarejestrowany

Homologowany fabrycznie

Termin badania technicznego **2022-12-10**

Kraj **Polska**

11.12.2019

Pierwsza rejestracja pojazdu

30.09.2019

Pojazd wyprodukowany

DZIENNIK SPRAWDZEŃ

Data i czas	Rodzaj usługi	IP	Lokalizacja
04.08.2022 07:08:07	Raport autoDNA	5.173.XXX.XXX	Warsaw, Poland
03.08.2022 05:08:48	Raport autoDNA	5.173.XXX.XXX	Poland
26.06.2022 08:06:02	Raport autoDNA	37.30.XXX.XXX	Warsaw, Poland

WYPOSAŻENIE

CLUSTER TYPE - SUPER VISION 4.2" TFT LCD	9401D5	RETRACTOR PRETENSIONER - ELECTRICAL TYPE	8885A2	DR SIDE W/STRIP - RUBBER(SILICON COAT'G)	8212A1
BACK LITE GLASS TYPE - PRIVACY(W/ HEATED	8712C2	ONE TOUCH - FLAT FOLD HANDLE - LUGGAGE S	85B5A1	STEER"G COLUMN-MANUAL TILT & TELESCOPIC	5631A4
TAIL GATE FINISH"G-FORMED TYPE(PLASTIC)	817AB3	UPR TRIM FINISH"G - TPO (THERMO PLASTIC	8232A8	DR BELT LINE MLD'G - BLACK-SUS+PVC TYPE	8223A2
SEAT WARMER (HEATER) - 3-STEPS (BUTTON)	8873B4	BODY SIDE W/STRIP-RUBBER(SILICON COATG)	8211A1	SEAT WARMER (HEATER) - 3-STEPS (BUTTON)	8838B4
CENTRAL DR LOCK/UNLOCK-DR"S & PA"S CTRL	8131A2	P/WINDOW RR DR - AUTO UP/DOWN & SAFETY	824CA6	TIRE PRESSURE MONITORG SYS - HIGH LINE	9574A1
LWR TRIM (MAIN TRIM)PLASTIC(NO COVERG)	82A8A1	P/WINDOW PA'S - AUTO UP/DOWN & SAFETY	824BA6	RR WIPER - INTERMITTENT(NON VARIABLE)	9871A1
SIDE AIR BAG-FR - FR(THORAX & PELVIS)	5693A3	LUMBAR SUPPORT - ELECT LUMBER SUPPORT	8828A2	P/WINDOW DR"S - AUTO UP/DOWN & SAFETY	8244A6
O.B.D(ON-BOARD DIAGNOSTICS) - E.O.B.D	2845A2	ARM REST COVER"G - ARTIFICIAL LEATHER	8236A3	SENSOR-AIR FLOWER - NON SPEED DENSITY	3921A1
PASS'S SIDE - ELECTRIC HTD-CONV(WIDE)	8762C5	BATTER CAPACITY AGM TYPE - 64AH (5HR)	3711C3	W/ STORAGE BOX ARM REST - STD(1 DIN)	846BA1
W/S GLASS TYPE-TINTED (W/ S/B,SOLAR)	8611B3	FUEL FILLER DR FINISH"G - BODY COLOR	8153A1	MUFFLER MAIN ASSY - SINGLE-CR COAT"G	2861A2
BUTTON START - BUTTON W/ ILLUMINATED	8196A2	POCKET LIGHTING - FRT DOOR - W/ILLUM	826DA1	AUTO LIGHT CONTROL SYSTEM - 1 STAGE	9511A1
SEAT BACK - SEAT BACK PNL(W/POCKET)	886BA3	FR SUSP TYPE - MACPH. W/COIL SPRING	5411A1	SHIFT LOCK SYSTEM - ELECTRONIC TYPE	4503A2
ESC (ELECTRONIC STABILITY CONTROL)	5894A1	VSM (VEHICLE STABILITY MANAGEMENT)	589GA1	CARRIER MATERIAL - PLASTIC(HYBRID)	6411A1
TAIL GATE OPEN'G DEVICE - GAS LIFT	8173A1	FUEL FILLER DR REL TYPE - ELECTRIC	8152A4	DRIVER"S - ELECTRIC HTD-CONV(WIDE)	8763C7
AUTO CRUISE CONTROL - CONVENTIONAL	9641A1	SPEAKER LOCATION RR DR LOW-GENERAL	963ZA1	TRUNK LID RELEASE TYPE - ELECTRIC	8123A3

FUEL FILLER DR MATERIAL - PLASTIC	8151A2	FR WIPER - INTERMITTENT(VARIABLE)	9811A2	A/CLOTH(CLOTH+ARTIFICIAL LEATHER)	8811B4
TPMS (TIRE PRESSURE MONITORG SYS)	94K3A1	RR SUSP TYPE - MULTI LINK-SPORTY	5511B2	TRUNK LID PANEL MATERIAL - STEEL	8121A1
DR FRAME GARNISH - BLACK(GLOSSY)	8225A2	BODY CONTROL MODULE - BCM(ETACS)	9541A1	FR COOLER - DUAL FULL AUTO A/CON	9761A6
TAIL GATE PANEL MATERIAL - STEEL	8172A1	ENGINE PACKAGE - VGT REGULAR ENG	0091A5	FREQUENCY VIBRATION - AM9K/FM50K	9615A3
AIR BAG LABEL(PAS'S) - PICTOGRAM	569BE1	IGNITION ILLUMINATED - BULB TYPE	8195A1	SPEAKER LOCATION FR DR - GENERAL	963CA1
CENTER TRIM - ARTIFICIAL LEATHER	8233E1	ROOF TRIM MATERIAL - CLOTH(STD)	8531A3	PRE TENSIONER - ELECTRICAL TYPE	888AA2
T/LID INSIDE HANDLE - HOOK TYPE	8125A2	ROOF - ROOF RACK - SILVER PAINT	8672A5	EU+AUSTRALIA TYPE - WIRING ONLY	2536A4
DR BELT LINE E/PIECE - NATURAL	8224A7	TEMPORARY - STEEL WHEEL & TIRE	5297C1	INSIDE HNDL OVER RIDE - ALL DR	8135A3
VOLUME KNOB TYPE - EUROPE TYPE	9616A1	HOOD OPENING DEVICE - GAS LIFT	8112A2	HAC (HILLSTART ASSIST CONTROL)	589HA1
AVERAGE FUEL CONSUMPTION(AFC)	965BA1	IMPACT SENS"G AUTO DR UNLOCKG	813BA1	HEAD REST - UP/DOWN & SLIDING	8854A5
HEAD REST - UP/DOWN & SLIDING	8821A5	VOICE RECOGNITION SYSTEM REMO	967FA1	FUEL TANK-CAPACITY - 70 LITER	3111D1
ONE TOUCH TRIPLE TURN SIGNAL	923DA1	TIRE PRESSURE LABEL - EUROPE	529AB1	ELECTRIC CHROMIC MIRROR TYPE	8511C1
SPEED LIMITER - DISPLAY TYPE	94X5A1	RR P/TRAY MATERIAL - W/PAPER	8561A2	LAMP TYPE - SEPARATED INSIDE	9245A2
RR HEATING DUCTS - 2ND SEAT	9741A1	CATALYTIC CONVERTER - D.P.F	2891F1	SMART KEY-TRUNK LID(T/GATE)	819KA1
MID-RANGE SPEAKER(STANDARD)	9635A2	FR DR GLASS - SOLAR CONTROL	8241A3	PADDLE SHIFTER - LEVER TYPE	967KA1
MULTIFUNCTION SW TYPE - LHD	9340A1	TRUNK LID TRIM - FULL COVER	8124A1	HOOD PANEL MATERIAL - STEEL	8111A1
ESS (EMERGENCY STOP SIGNAL)	5896A1	IGN KEY REMOVG AT DR UNLOCK	813XA1	LICENCE PLATE - EUROPE TYPE	6921D1
VANITY MIRROR - GLASS TYPE	852GA1	ADJUSTER - HEIGHT ADJUSTER	8857A2	LEVER FINISH"G - CR COAT"G	8262A2
S/BELT ANCHOR - ADJUSTABLE	888RA2	CENTRAL T/GATE LOCK/UNLOCK	8177A1	VANITY MIRROR - GLASS TYPE	8522A1
RR QTR GLASS TYPE -PRIVACY	8791C1	S/BELT ANCHOR - ADJUSTABLE	888KA2	O/SIDE TEMPERATURE DISPLAY	965QA1
PASSENGER SIDE - DEPOWERED	5692A3	DR AJAR - DR OPEN POSITION	94DOA2	ADJUSTER - HEIGHT ADJUSTER	8825A2

AVERAGE VEHICLE SPEED(AVS)	965CA1	REFRIGERATOR - ALTERNATIVE	9768A2	TIRE SOURCE - CONTINENTAL	5294B9
SPEED SENS"G AUTO DR LOCK	813AA1	MLD"G-S/SILL - BODY COLOR	8772B1	CHILD SAFETY RR DR LOCK"G	8136A1
KEY TYPE - INSIDE CUTTING	8191A2	AT KNOB - LEATHER WRAPPED	4371B3	FINISH"G - HALF CR COAT"G	8261A3
LUGGAGE FLOOR RAIL SYSTEM	85B4A1	ANTI-CORROSION TREATMENT	8648A1	B TYPE - BLACK+CR COAT"G	8631B4
TAIL GATE TYPE - LIFT UP	8171A1	SUSPENSION SPEC - EUROPE	541BA2	DRL - DEDICATED LED TYPE	9213A4
SINGLE BOOSTER - 11 INCH	5911A6	WASHER FLUID WARN"G LAMP	94G0A1	STEER"G LOCK TYPE - ESCL	8198A3
CUP HOLDER - FR(W/O ILL)	8462A1	DLX - ARTIFICIAL LEATHER	8461B4	DISTANCE TO EMPTY(D.T.E)	965AA1
RR BRAKE - DISC-15 INCH	5812A8	TYPE - INTERGRATED TYPE	9651A2	INSTANT FUEL CONSUMPTIO	965EA1
DRIVER SIDE - DEPOWERED	5691A3	ABS (ANTI LOCK BRK SYS)	5891A2	ELECTRIC FOLD"G CONTROL	876MA1
FR BRAKE - DISC-16 INCH	5811A5	FENDER MATERIAL - STEEL	6631A1	SEAT BACK PNL(W/POCKET)	8836A3
INTEGRATED - CLEAR LENS	9231B1	MAP POCKET TYPE - FIXED	82B5A1	SPEEDOMETER TYPE - KMPH	94M0A1
DELAY OUT INTERIOR LAMP	928KA1	INTERIOR LAMP - AUTOCUT	371FA1	T/LID EMERGENCY RELEASE	812AA1
LEVELING DEVICE - AUTO	921BA2	A/T POSITION INDICATOR	94C1A1	MUFFLER MATERIAL - SUS	2865A2
TIE DOWN HOOK(LASHING)	8642A1	TRUNK LID(T/GATE) OPEN	94D7A1	LUGGAGE SIDE - W/PAPER	8571C1
PASSENGER"S SIDE - ELR	8884D1	DUAL HORN - SHELL TYPE	9661B2	DR FRAME MLDG - BRIGHT	8221A2
L.D.C CONVERTER - 200W	3734A1	TIRE MATERIAL - SILICA	5295A2	SPEED LIMITER - A TYPE	964LA1
RR DR GLASS - PRIVACY	8245A5	NOZZLE - SPRAY WASHER	9851A1	MATERIAL - CLOTH(STD)	8523A3
MATERIAL - CLOTH(STD)	8521A3	FUNCTION - AIR FILTER	9714A1	SAPARATED-INSIDE LAMP	9246A1
PARKG BRK CONTROL-EPB	5971A4	LED (DYNAMIC BENDING)	921KA2	DRIVER'S KNEE AIR BAG	5697A1
215 TIRE - 215/55 R17	5293GC	KEYLESS ENTRY-B/ALARM	819AA1	TEMPERATURE UNIT - C	94N0A1
KEYLESS ENTRY-T/OPEN	819CA1	BRAKE PAD - EUROPEAN	5813A2	H.M.S.L - T/GATE INR	8722A2

ISO FIX CHILD ANCHOR	892RA1	DRIVER'S SIDE - ELR	8881B1	HOLDER - UPR ANCHOR	892DA1
KEY OPERATED WARN"G	9684A1	DIRECTION INDICATOR	94C6A1	ENGINE COVER - FULL	2921A4
N/PUNCH - FLAT TYPE	8421D1	TYPE - SLIDING TYPE	852EA2	VANITY MIRROR COVER	852HA1
TYPE - SLIDING TYPE	852LA2	VANITY MIRROR COVER	852BA1	PTC HEATER_INT TYPE	9713A2
PARK"G BRAKE WARN"G	9686A1	MTG TYPE - BOLTING	6412A2	SEAT BELT REMINDER	888DA1
SEAT BELT REMINDER	8889A1	LCD ODO/TRIP METER	940EA1	RR HEATED W/ TIMER	871BA1
COLOR - BODY COLOR	8765A2	AUTO LIGHT CONTROL	9219A1	FR - W/ SUNGLASSES	9282A1
COLOR - BODY COLOR	8652B1	SIDE REPEATER LAMP	876NA1	BULB TYPE - 2 BULB	928WA2
MLD"G - BODY COLOR	8731B1	KICKDOWN MECHANISM	327AA1	FLOOR - WALL PAPER	8573A2
SAFETY BARRIER NET	857NA1	3-SPOKE - LEATHER	5611B3	RR - CONVENTIONAL	9222A1
PAB ON/OFF SWITCH	569EA1	LH/RH - BJ95+TJ95	4951B6	T/LID HINGE COVER	812EA1
SECURITY INDICATE	813MA1	VOICE RECOGNITION	965VA1	BATTERY UPR COVER	371AA1
FORMED TYPE - STD	8231B1	HYDROPHOBIC GLASS	8242A1	AUTO DEFOG SYSTEM	972MA1
CONSOLE UPR COVER	84H4A1	LED POSITION TYPE	921LA1	BLADE TYPE - AERO	9819A2
FR WIPER-2 SPEED	981AA1	MAP POCKET-RR DR	82A7A1	ELAPSE TIME(E/T)	965DA1
IGN KEY REMINDER	813DA1	HTR CONTROL KNOB	84FEA1	COMPONENT - 2 DIN	9614B1
LUGGAGE NET HOOK	8578A1	ACTIVE ECO - S/W	94X9A1	MAP POCKET-FR DR	82A5A1
BLUE TOOTH REMO	967EA1	DOUBLE PIPE IHX	9763A1	AUTO STOP (ISG)	94X4A1
WATER SEPARATER	94H2A1	TOWING HOOK(FR)	864JA1	RR - WALL PAPER	8572A3
CTR UNDER COVER	8411A1	DOUBLE RECLIN"G	885EA2	W/ WIPER DEICER	86A1A1
SMART KEY-FR DR	819HA1	DOUBLE RECLIN"G	8824A2	TOWING HOOK(RR)	864KA1

RR POWER OUTLET	8464A1	TYPE - 2.5 MILE	8651B1	LENS TYPE - LED	8723A2
ROLLOVER SENSOR	569HA1	S/BELT REMINDER	898JA1	VIN LABEL - VIN	864EA1
BATTERY CHARGE	94D1A1	CONSOLE A/VENT	974AA1	GLOW INDICATOR	94G5A1
TYPE - DIGITAL	9451A1	LUGGAGE SCREEN	8571A1	FLOOR MTG TYPE	3283A1
A PILLAR - STD	858AA1	AMBIENT SENSOR	971BA1	C PILLAR - STD	858CA1
D PILLAR - STD	858EA1	MIRROR FOLDING	819LA1	DR SCUFF - STD	858RA1
HOOD INSULATOR	811AA1	CRUISE CONTROL	94F3A1	B PILLAR - STD	858BA1
GEAR POSITION	94C2A1	ENG OIL LEVEL	94H8A1	FOG LAMP (FR)	94G4A1
REMOTE FOLD"G	89E4A1	CURTAIN A/BAG	5695A1	MIST FUNCTION	9817A1
O/SIDE HANDLE	812BA1	BATTERY SAVER	371CA1	TICKET HOLDER	852AA1
NON LED TYPE	9241A2	DRINK HOLDER	89C1A1	CHECK ENGINE	94D9A1
LOAD LIMITER	889MA1	LOAD LIMITER	888EA1	POWER OUTLET	857AA1
LUGGAGE LAMP	9287A1	CTR AIR VENT	84FDA1	PARK"G BRAKE	94C9A1
OIL PRESSURE	94C7A1	MUD GUARD-FR	8681A1	MUD GUARD-RR	8682A1
ILLUMINATED	852DA1	LUGGAGE NET	8579A1	ILLUMINATED	852KA1
IMMOBILIZER	94H6A1	IMMOBILIZER	9542A1	AUDIO REMO.	967AA1
SPEEDOMETER	9402A1	RR FOG LAMP	94D5A1	RAIN SENSOR	9815A1
WATER TEMP.	940DA1	SET CONTROL	94F4A1	W/ MAP LAMP	9297A1
AUDIO KNOB	84FCA1	TAIL LIGHT	94W1A1	SIDE - ELR	8981A4
HIGH GRADE	6501A1	TACHOMETER	940BA1	W/ HEATED	561AA1
RR - 2 EA	853AA2	W/ DAMPER	8452A2	FR - LAMP	928HA1

CTR - ELR	8982A4	ACC REMO.	967BA1	FR - 1 EA	8532A1
SEAT BELT	9681A1	RR - 1 EA	853JA1	E.S.P OFF	94J0A1
SEAT BELT	94E3A1	BRAKE OIL	94C8A1	HIGH BEAM	94D2A1
LOW BEAM	94D3A1	LOW FUEL	94D4A1	W/ ILLUM	845BA1
RHEOSTAT	9491A1	USB+AUX	9618A1	SLIDING	885DA1
FOB KEY	819GA1	L.K.A.S	9579A2	W/ LOCK	8451A2
SLIDING	8823A1	H-MATIC	4509A1	W/O BOX	89B1A1
ESCORT	921JA1	A.B.S	94E5A1	E.S.P	94H9A1
A/BAG	94E6A1	FUEL	940CA1	MDPS	94H7A1
Opis --	957LA3	Opis --	5291XG	Opis --	9556A1
Opis --	9221F2	Opis --	9211G2	Opis --	857RA2
Opis --	9767A3	Opis --	979EA5	Opis --	8122A4
Opis --	WT 2	Opis --	882BA3	Opis --	967LA2
Opis --	824HA5	Opis --	8912H1	Opis --	885CA3
Opis --	8778B3	Opis --	8665A2	Opis --	8654A1
Opis --	863AF3	Opis --	857WA1	Opis --	8471C1
Opis --	824RE2	Opis --	824PE2	Opis --	824GE2
Opis --	8918B1	Opis --	823IA3	Opis --	819DA1
Opis --	7932A3	Opis --	7931A3	Opis --	5711B2
Opis --	5512A7	Opis --	5412A7	Opis --	3731B4
Opis --	2841B9	Opis --	0101B9	Opis --	8917B1

Opis --	8919B1	Opis --	967HA1	Opis --	928FB5
Opis --	965TA1	Opis --	9627A1	Opis --	961NF7
Opis --	961KA1	Opis --	9611ZD	Opis --	959RA3
Opis --	959NA3	Opis --	9552E1	Opis --	9549A1
Opis --	94XGA1	Opis --	915NA1	Opis --	892XA1
Opis --	915MA1	Opis --	915LA1	Opis --	915EA1
Opis --	915DA1	Opis --	915CA1	Opis --	915BA1
Opis --	915AA1	Opis --	89B3A1	Opis --	898DA1
Opis --	898AA1	Opis --	957SA1		

ARCHIWALNE ZDJĘCIA POJAZDU

24.06.2022

Liczba zdjęć 32












21.03.2022

Liczba zdjęć 32









Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez AUTODNA Sp. z o.o. o tym fakcie. AUTODNA Sp. z o.o. nie ponosi odpowiedzialności za treść danych zawartych w Raportach. Treść taka może być niepełna lub niezgodna ze stanem rzeczywistym.

Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody AUTODNA Sp. z o.o.

AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiejkolwiek formie.


AUTODNA Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez AUTODNA Sp. z o.o. w jakiejkolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.


autoDNA**Raport Historii Pojazdu autoDNA****Zeskanuj mnie!**

KNAGU819GL5387986

Kia OPTIMA

**Jak skanować QR kod**

Uruchom aparat w swoim telefonie i skieruj obiektyw telefonu na kod QR. Telefon automatycznie zeskanuje QR kod. Alternatywnie, uruchom aplikację do skanowania QR i postępuj analogicznie.

**Jak nakleić na szybę**

Naklej na boczną szybę samochodu, po prawej lub lewej stronie. Nie rekomendujemy naklejania na przednią szybę, która ustawiona jest pod kątem przez co trudniej będzie zeskanować QR kod.

**Jak umieścić zdjęcie w ogłoszeniu**

Dodaj QR kod jako kolejne zdjęcie do swojego ogłoszenia. Popularne serwisy umożliwiają dodawanie zdjęcia w rozmiarze do 5 MB o rozdzielczości 1080 x 720 px. Plik, który otrzymałeś od nas wraz z zamówionym raportem spełnia te wymagania. Po prostu dodaj zdjęcie do galerii sprzedawanego pojazdu.