



## Raport Historii Pojazdu autoDNA

Raport zawiera dostępne informacje na dzień: 2023-03-25 21:40:47 UTC +0100

Wersja językowa: PL

0a3c42de-2713a1f9-fec6f6cc-960fde42-a3929b49



Hyundai SANTA FE  
KMHSW81UDHU732057

### Wiek pojazdu

Wg daty produkcji / roku modelowego

7 LAT(A) 2 MIES.

Data produkcji / Rok modelowy 2016

Wg pierwszej rejestracji pojazdu

6 LAT(A) 1 MIES.

Data pierwszej rejestracji 2017-02-02

1 2 6 4 5 7 km

**Uwaga:** Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

## CENTRUM POWIADOMIEŃ

### Bazy Skradzionych Pojazdów

✓ Przeszukane bazy 12/12

### Akcje serwisowe

✓ Nie odnotowano

### Informacje o pojeździe

i Liczba wpisów 19

### Dziennik użytkowania

i Liczba wpisów 9


### Historia cenowa

i Nie odnotowano


### Odczyty drogomierza

✓ Liczba wpisów 4


## Historia uszkodzeń

 Liczba wpisów 1


## Wyposażenie

 Liczba wpisów 363

## Archiwalne zdjęcia

 Liczba wpisów 18

## Poprawność VIN

 Niedostępne

## INFORMACJE O POJEŹDZIE

**Producent**  
HYUNDAI**Typ paliwa**  
DIESEL**Rok modelowy**  
2016**Próbka koloru lakieru**  
**Silnik**  
2.0L DOHC TCI**Napęd**  
4WD**Średnie spalanie [l/100km]**  
8.72**Model**  
SANTA FE**Pojemność silnika [cm3]**  
2000**Kod koloru lakieru**  
W8U**Kod koloru wnętrza**  
VYN**Typ skrzyni biegów**  
AUTOMATYCZNA**Kod modelu**  
KEURPDM15**Rodzaj nadwozia**  
SUV**Kraj producenta**  
KOREA POŁUDNIOWA**Kolor lakieru**  
OCEAN VIEW**Data produkcji**  
2016**Skrzynia biegów**  
6-BIEGOWA**Rynek przeznaczenia**  
C27, POLAND

## AKCJE SERWISOWE



Nie odnotowano

# BAZA SKRADZIONYCH POJAZDÓW

Przeszukane bazy 12

Odnotowano 0

 **Włochy**

Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Czechy**

Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Rumunia**

Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Litwa**


Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Słowenia**

Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Holandia**

Ewidencja pojazdów skradzionych - Repozytoria Crimimail oraz Stowarzyszenie Ubezpieczycieli

✓ Nie odnotowano

 **Kanada**

Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Słowacja**

Ewidencja pojazdów skradzionych - Policja

✓ Nie odnotowano

 **Szwecja**

Ewidencja pojazdów skradzionych - Stowarzyszenie Ubezpieczycieli

✓ Nie odnotowano

 **Norwegia**

Ewidencja pojazdów skradzionych - Ettersokt

✓ Nie odnotowano

 **Kaynine**

Ewidencja przedmiotów skradzionych - Kaynine(Niemcy)

✓ Nie odnotowano

 **Baza int.**

Ewidencja pojazdów skradzionych - Niezależne źródła internetowe

✓ Nie odnotowano

## HISTORIA POJAZDU

2023

02.02.2023

**Ubezpieczenie pojazdu**

Polisa ważna do **2024-02-01**

Kraj **Polska**

## 2022

14.08.2022

Zgłoszono odczyt drogomierza

Stan drogomierza  
146 549 km

15.07.2022

Wykonano okresowe badanie techniczne

Stan drogomierza  
146 486 km

Wynik **Pozytywny**  
Termin badania technicznego **2023-07-15**  
Kraj **Polska**

02.02.2022

Ubezpieczenie pojazdu

Polisa ważna do **2023-02-01**  
Kraj **Polska**

21.01.2022

Przerejestrowanie pojazdu, ze względu na zmianę własności

Zarejestrowany na osobę fizyczną  
Miejsce rejestracji **Grudziądz, kujawsko-pomorskie**  
Kraj **Polska**

## 2021

26.07.2021

Wykonano okresowe badanie techniczne

Stan drogomierza  
126 195 km

Wynik **Pozytywny**  
Termin badania technicznego **2022-07-26**  
Kraj **Polska**

27.04.2021

Przeprowadzenie kontroli drogowej pojazdu

Stan drogomierza  
121 405 km

Kraj **Polska**

02.02.2021

Ubezpieczenie pojazdu

Polisa ważna do **2022-02-01**  
Kraj **Polska**

## 2020

02.02.2020

Ubezpieczenie pojazdu

Polisa ważna do **2021-02-01**

Kraj **Polska**

## 2019

05.2019

Odnotowano szkodę na pojeździe

Kwota **2500 - 3000 PLN**

Rezultat

 **USZKODZENIE NADWOZIA**

Grupa części

- Elementy karoserii zewnętrznej
- Oświetlenie zewnętrzne

Kraj **Polska**



Strefa uszkodzenia

- Tył
- Lewy tył

## 2017

02.02.2017

Pojazd zarejestrowany

Homologowany fabrycznie

Katalizator

Termin badania technicznego **2020-02-01**

Kraj **Polska**

02.02.2017

Pierwsza rejestracja pojazdu

31.01.2017

Rozpoczęcie okresu gwarancyjnego

## 2016

18.10.2016

Pojazd wyprodukowany

# DZIENNIK SPRAWDZEŃ

Data i czas	Rodzaj usługi	IP	Lokalizacja
--	-	--	--

## WYPOSAŻENIE

CLASSIFICATION FOR PERSON - FOR 3 PEOPLE 891JB2	SEAT WARMER (HEATER) - HIGH/LOW - PUSH R 892WB3	CLUSTER TYPE - SUPER VISION 4.2" TFT LCD 9401D5
RETRACTOR PRETENSIONER - ELECTRICAL TYPE 8885A2	BACK LITE GLASS TYPE - PRIVACY(W/ HEATED) 8712C2	PANORAMA SUNROOF - POWER-ONE TOUCH SAFET 816PA2
ONE TOUCH - FLAT FOLD HANDLE - LUGGAGE S 85B5A1	CENTER TRIM - TPO (THERMO PLASTIC OLEFIN) 8233P1	SEAT WARMER (HEATER) - 3-STEPS (BUTTON) 8838B4
SEAT WARMER (HEATER) - 3-STEPS (BUTTON) 8873B4	UPR TRIM FINISH'G - TPO (THERMO PLASTIC) 8232AB	TAIL GATE FINISH"G-FORMED TYPE(PLASTIC) 817AB3
P/WINDOW RR DR - AUTO UP/DOWN & SAFETY 824CA6	LWR TRIM (MAIN TRIM)PLASTIC(NO COVERG) 82ABA1	TIRE PRESSURE MONITORG SYS - HIGH LINE 9574A1
STEER"G COLUMN-MANUAL LWR TILT & TELES 5631A6	P/WINDOW PA'S - AUTO UP/DOWN & SAFETY 824BA6	P/WINDOW DR"S - AUTO UP/DOWN & SAFETY 824AA6
SIDE AIR BAG-FR - FR(THORAX & PELVIS) 5693A3	ARM REST COVER"G - ARTIFICIAL LEATHER 8236A3	RR WIPER - INTERMITTENT(NON VARIABLE) 9871A1
CENTRAL DR LOCK/UNLOCK - DR'S CONTROL 8131A1	W/ STORAGE BOX ARM REST - STD(1 DIN) 846BA1	FUNCTION - WASHER FLUID LEVEL SENSOR 9852A1
POCKET LIGHTING - FRT DOOR - W/ILLUM 826DA1	W/S GLASS TYPE-TINTED (W/ S/B,SOLAR) 8611B3	ACTIVE HOOD SYSTEM - 2 CORNER POP-UP 8115A1
BUTTON START - BUTTON W/ ILLUMINATED 8196A2	T/F TYPE - ELECTRONIC ON-DEMAND TYPE 4731A4	FR SUSP TYPE - MACPH. W/COIL SPRING 5411A1
SHIFT LOCK SYSTEM - ELECTRONIC TYPE 4503A2	SPEAKER LOCATION QUADRANT INR COVER 963MA1	MUFFLER TAIL TRIM - SINGLE TWIN TIP 2862A3
FUEL FILLER DR REL TYPE - ELECTRIC 8152A4	ESC (ELECTRONIC STABILITY CONTROL) 5894A1	CONSOLE COVER - ARTIFICIAL LEATHER 846LA3
SPEAKER LOCATION RR DR LOW-GENERAL 963ZA1	ANTENNA TELESCOPIC - ANTENNA MICRO 9621K1	VSM (VEHICLE STABILITY MANAGEMENT) 589CA1
FR WIPER - INTERMITTENT(VARIABLE) 9811A2	DRIVER'S SIDE - ELECTRIC HTD-CONV 8763C4	TPMS (TIRE PRESSURE MONITORG SYS) 94K3A1
DR FRAME GARNISH - BLACK(GLOSSY) 8225A2	FR COOLER - DUAL FULL AUTO A/CON 9761A6	IGNITION ILLUMINATED - BULB TYPE 8195A1
2ND SEAT BACK TYPE - 4:2:4 SPLIT 891LB4	SPEAKER LOCATION FR DR - GENERAL 963CA1	AIR BAG LABEL(PAS'S) - PICTOGRAM 569BE1

FREQUENCY VIBRATION - AM9K/FM50K	9615A3	ID PLATE - EUROPE('E' MARK) TYPE	8649A5	BODY CONTROL MODULE - BCM(ETACS)	9541A1
ENGINE PACKAGE - VGT REGULAR ENG	0091A5	RR SUSP TYPE - MULTI LINK-NORMAL	5511B1	P/WINDOW SW - ILLUMINATION(ALL)	824FC1
SPEED LIMITER REMO - LEVER TYPE	9671A1	LEVELING DEVICE - AUTO(DYNAMIC)	921BA3	ROOF TRIM MATERIAL - CLOTH(STD)	8531A3
TAIL GATE OPEN'G DEVICE - POWER	8173A2	PRE TENSIONER - ELECTRICAL TYPE	888AA2	EU+AUSTRALIA TYPE - WIRING ONLY	2536A4
PASS'S SIDE - ELECTRIC HTD-CONV	8762C4	FULL SIZE 1EA - AL WHEEL & TIRE	5297A3	2ND SEAT CUSH TYPE - 6:4 SPLIT	891KB2
TOOL SET & JACK LABEL - EUROPE	5297A7	INSIDE HNDL OVER RIDE - ALL DR	8135A3	TSA (TRAILER STABILITY ASSIST)	5898A1
HAC (HILLSTART ASSIST CONTROL)	589HA1	O/HEAD CONSOLE TYPE - STANDARD	9295A1	HOOD OPENING DEVICE - GAS LIFT	8112A2
FREQUENCY-SMART KEY - GENERAL	9545A3	FUEL TANK CAPACITY - 64 LITER	3111A9	HEAD REST - UP/DOWN & SLIDING	8854A5
HEAD REST - UP/DOWN & SLIDING	8821A5	IMPACT SENS'G AUTO DR UNLOCKG	813BA1	MLD'G-WINDSHIELD - BODY COLOR	8612A3
AVERAGE FUEL CONSUMPTION(AFC)	965BA1	DBC (DOWNHILL BRAKE CONTROL)	589AA1	SEAT BACK - SEAT BACK POCKET	886BA1
FR SKID PLATE - PLASTIC TYPE	8661A1	TIRE PRESSURE LABEL - EUROPE	529AB1	LANE DEPARTURE WARN'G SYSTEM	9579A1
SPEED LIMITER - DISPLAY TYPE	94X5A1	ONE TOUCH TRIPLE TURN SIGNAL	929DA1	P/BRAKE KNOB TRIM - SOFT PVC	5972A1
DBC (DOWNHILL BRAKE CONTROL)	94J1A1	EXTERNAL CONTROL COMPRESSOR	979EA1	AUTO CRUISE CONTROL - SMART	9641A2
RR HEATING DUCTS - 2ND SEAT	9741A1	F.F.H.S(FUEL FILTER HEAT'G)	3914A1	RR SPOILER W/ HMSL - A TYPE	8721B1
BRIGHT-TRANSFORMED(PARTING)	8221B2	FR DR GLASS - SOLAR CONTROL	8241A3	BAS(BRAKE ASSISTANT SYSTEM)	5895A1
ESS (EMERGENCY STOP SIGNAL)	5896A1	CATALYTIC CONVERTER - D.P.F	2891F1	PASSENGER SIDE - DEPOWERED	5692A3
SPEAKER LOCATION CENTER-FR	963EA1	RR QTR GLASS TYPE -PRIVACY	8791C1	UNDER COVER - W/ NOISE PAD	2911A1
VANITY MIRROR - GLASS TYPE	8522A1	CENTRAL T/GATE LOCK/UNLOCK	8177A1	T/GATE KEY CENTRAL DR LOCK	8178A1
L.D.C CONVERTER - 200+400W	3734A4	S/BELT ANCHOR - ADJUSTABLE	888RA2	ADAPTIVE FR LIGHT'G SYSTEM	94J8A1
REFRIGERATOR - ALTERNATIVE	9768A2	VANITY MIRROR - GLASS TYPE	852GA1	PROJECTION-LOW BEAM-A TYPE	9211F1
AVERAGE VEHICLE SPEED(AVS)	965CA1	LEVER FINISH'G - CR COAT'G	8262A2	S/BELT ANCHOR - ADJUSTABLE	888KA2
CONVENTIONAL - CLEAR LENS	9221A2	AT KNOB - LEATHER WRAPPED	4371B3	SPEED SENS'G AUTO DR LOCK	813AA1

CHILD SAFETY RR DR LOCK"G	8136A1	WASHER FLUID WARN"G LAMP	94G0A1	DRL - DEDICATED LED TYPE	9213A4
COLOR - TWO TONE NATURAL	8652D2	ANTI-CORROSION TREATMENT	8648A1	DISTANCE TO EMPTY(D.T.E)	965AA1
CIGAR LIGHTER - W/ ILLUM	8445A2	SPEAKER - SURROUND SOUND	963YA1	INVERTER - 220V INVERTER	9431A2
SINGLE BOOSTER - 11 INCH	5911A6	CUP HOLDER - FR(W/O ILL)	8462A1	STEER'G LOCK TYPE - ESCL	8198A3
O/SIDE TEMPERATURE GAUGE	972DA1	SPEAKER BRAND - PREMIUM	963VB1	RR SKID PLATE - PLASTIC	8665A1
MLD"G-BACK LITE - BLACK	8711A1	DRIVER SIDE - DEPOWERED	5691A3	ELECTRIC FOLD"G CONTROL	876MA1
TYPE - INTERGRATED TYPE	9651A2	S/ABSORBER TYPE - H.P.D	5512A4	S/ABSORBER TYPE - H.P.D	5412A4
FR BRAKE - DISC-17 INCH	5811A6	RR BRAKE - DISC-16 INCH	5812A9	ABS (ANTI LOCK BRK SYS)	5891A2
LUGGAGE UNDER FLOOR BOX	857HA1	SPEEDOMETER TYPE - KMPH	94M0A1	DELAY OUT INTERIOR LAMP	928KA1
TRUNK LID(T/GATE) OPEN	94D7A1	TIE DOWN HOOK(LASHING)	8642A1	TIRE SOURCE - HAN KOOK	5294A1
SPEED LIMITER - A TYPE	964LA1	A/T POSITION INDICATOR	94C1A1	SEPARATED - CLEAR LENS	9231A1
LUMBAR SUPPORT - 4 WAY	8828A3	PASSENGER"S SIDE - ELR	8884D1	LUGGAGE SIDE - PLASTIC	8571B1
RR DR GLASS - PRIVACY	8245A5	PARKG BRK CONTROL-EPB	5971A4	KEYLESS ENTRY-B/ALARM	819AA1
TIME LAG POWER WINDOW	824DA1	CURTAIN - MANUAL TYPE	823BA1	T/C PILE - CARPET_DLX	8421E2
ELEC TYPE - FATC TYPE	9721F1	FUNCTION - AIR FILTER	9714A1	DUAL HORN - DISK TYPE	9661B1
235 TIRE - 235/55 R19	5293JC	MATERIAL - CLOTH(STD)	8523A3	MATERIAL - CLOTH(STD)	8521A3
DRIVER'S KNEE AIR BAG	5697A1	ANCHOR PRE TENSIONER	8881A1	MLD"G-S/SILL - BLACK	8772A1
TIRE SOURCE - KUM HO	5294A2	BLOWER - 4 SPEED FAN	9711A2	TEMPERATURE UNIT - C	94N0A1
BRAKE PAD - EUROPEAN	5813A2	FINISH"G - CR COAT"G	8261A4	AIR VENTILATION SEAT	885NA1
AIR VENTILATION SEAT	8841A1	GARNISH-SIDE - BLACK	8775A1	ANCHOR PRE TENSIONER	888HA1
SMART CRUISE CONTROL	94F3A2	MAKER MARK - HYUNDAI	863BA1	TYPE - SLIDING TYPE	852EA2



DRIVER'S SIDE - ELR	8881B1	ENGINE COVER - SEMI	2921A2	HOLDER - UPR ANCHOR	892DA1
TIRE SOURCE - NEXEN	5294A3	PTC HEATER_INT TYPE	9713A2	A/BAG OFF INDICATOR	94E7A1
PARK"G BRAKE WARN"G	9686A1	CORNER'G LIGHT - W/	9220A1	TYPE - SLIDING TYPE	852LA2
DIRECTION INDICATOR	94C6A1	VANITY MIRROR COVER	852HA1	VANITY MIRROR COVER	852BA1
FR BUMPER LIP - W/	865EA2	SEAT BELT REMINDER	8889A1	FR - W/ SUNGLASSES	9282A1
BULB TYPE - 2 BULB	928WA2	EXTERNAL AMP - AMP	963WA1	SEAT BELT REMINDER	888DA1
AUTO LIGHT CONTROL	9219A1	B TYPE - CR COAT"G	8631B3	LCD ODO/TRIP METER	940EA1
RR HEATED W/ TIMER	871BA1	SIDE REPEATER LAMP	876NA1	COLOR - BODY COLOR	8765A2
KICKDOWN MECHANISM	327AA1	MLD"G - BODY COLOR	8731B1	BACK WARN"G CAMERA	9652A1
POWER SEAT (I.M.S)	8849A1	TYPE - EC 2.5 MILE	8651F1	BLADE TYPE - AERO	9819A2
FORMED TYPE - STD	8231B1	PAB ON/OFF SWITCH	569EA1	DR AJAR - DR AJAR	94D0A1
GLOVE BOX-COOLING	845DA1	SECURITY INDICATE	813MA1	4-SPOKE - LEATHER	5611C3
RR - CONVENTIONAL	9222A1	AUTO DEFOG SYSTEM	972MA1	LED POSITION TYPE	921LA1
SEAT BACK POCKET	8836A1	MAP POCKET-RR DR	82A7A1	IGN KEY REMINDER	813DA1
FR WIPER-2 SPEED	981AA1	FR IMPACT SENSOR	569CA1	SPEAKER - WOOFER	963SA1
MAP POCKET-FR DR	82A5A1	ECM+COMPASS TYPE	8511E1	FENDER INSULATOR	8412A1
FLOOR - T/C PILE	8573A4	LUGGAGE NET HOOK	8578A1	ROLLOVER SENSOR	569HA1
CTR - GLOW LAMP	928FA1	LUGGAGE SIDE RH	857GA1	DOUBLE PIPE IHX	9763A1
SMART KEY-FR DR	819HA1	CLUSTER IONIZER	9717A1	PAB ON/OFF LAMP	569JA1
BLUE TOOTH REMO	967EA1	W/ WIPER DEICER	86A1A1	CENTER UPR TRAY	84F4A1
WATER SEPARATER	94H2A1	RR POWER OUTLET	8464A1	CTR UNDER COVER	8411A1



FINISH - PAINT	972LA1	FLOOR MTG TYPE	3283A1	GLOW INDICATOR	94G5A1
TYPE - DIGITAL	9451A1	BATTERY CHARGE	94D1A1	HOOD INSULATOR	811AA1
W/ PUDDLE LAMP	87A1A1	A PILLAR - DLX	858AA2	STABILIZER BAR	5414A1
D PILLAR - STD	858EA1	C PILLAR - DLX	858CA2	B PILLAR - DLX	858BA2
DR SCUFF - DLX	858RA2	MIRROR FOLDING	819LA1	TICKET HOLDER	852AA1
CURTAIN A/BAG	5695A1	FR - PORTABLE	8441A5	BATTERY SAVER	371CA1
WHL ARCH MLDG	877FA1	ACOUSTIC FILM	86A2A1	ENG OIL LEVEL	94H8A1
W/ CUP HOLDER	89F1A1	FOG LAMP (FR)	94G4A1	H/LAMP WASHER	9214A1
W/ SUNROOF SW	9299A1	ECO INDICATOR	94X2A1	B-PILLAR VENT	974BA1
CARGO SCREEN	857QA1	PARK"G BRAKE	94C9A1	CHECK ENGINE	94D9A1
LOAD LIMITER	889MA1	LOAD LIMITER	888EA1	POWER OUTLET	8467A1
OIL PRESSURE	94C7A1	MUD GUARD-FR	8681A1	MUD GUARD-RR	8682A1
PURE LEATHER	8811E2	WINDOW TRIM	817BA1	IMMOBILIZER	9542A1
ILLUMINATED	852KA1	LUGGAGE NET	8579A1	RAIN SENSOR	9815A1
TOWING HOOK	8641A1	AUDIO REMO.	967AA1	ILLUMINATED	852DA1
GRADE - GLS	863CA2	WATER TEMP.	940DA1	IMMOBILIZER	94H6A1
RR FOG LAMP	94D5A1	4WD LOCKING	940JA1	SPEEDOMETER	9402A1
SET CONTROL	94F4A1	CUP HOLDER	85ABA1	SIDE - ELR	8981A4
POWER SEAT	8827A1	STEP PLATE	858SA1	LWR ANCHOR	892CA1
CARGO LAMP	928LA1	TACHOMETER	940BA1	HIGH GRADE	6501A1
POWER SEAT	8862A1	HIGH BEAM	94D2A1	CTR - ELR	8982A4

W/ DAMPER	8452A2	ACC REMO.	967BA1	ROOF RACK	8672A1
W/ HEATED	561AA1	FR - LAMP	928HA1	E.S.P OFF	94J0A1
RR - 1 EA	853JA1	RR - 2 EA	853AA2	FR - 1 EA	8532A1
BRAKE OIL	94C8A1	MOOD LAMP	928MA1	SEAT BELT	94E3A1
LED TYPE	9241A3	LOW FUEL	94D4A1	RHEOSTAT	9491A1
W/ ILLUM	845BA1	USB+AUX	9618A1	W/ LOCK	8451A2
H-MATIC	4509A1	ESCORT	921JA1	A/BAG	94E6A1
E.S.P	94H9A1	I.M.S	876BA2	A.B.S	94E5A1
MDPS	94H7A1	MDPS	5711A6	FUEL	940CA1
4WD	940KA1	CTR	8915A1	EPB	94X3A1
RH	892EA1	RH	8914A1	LH	8921A1
LH	8913A1	Opis --	589BA1	Opis --	589CA1
Opis --	589DA1	Opis --	957AA2	Opis --	957GA1
Opis --	965YA1	Opis --	957HA1	Opis --	WT 2
Opis --	5291XQ	Opis --	9216B4	Opis --	2841B8
Opis --	3711C6	Opis --	3731B4	Opis --	819RA1
Opis --	823UB9	Opis --	8481C2	Opis --	94J5A1
Opis --	965TA1	Opis --	94XEA1	Opis --	9549A1
Opis --	9552E1	Opis --	9571A7	Opis --	957EA1
Opis --	9611ZD	Opis --	961NFD	Opis --	967JA1

# ARCHIWALNE ZDJĘCIA POJAZDU

15.08.2022

Liczba zdjęć 10



14.08.2022

Liczba zdjęć 8



### Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez AUTODNA Sp. z o.o. o tym fakcie. Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody AUTODNA Sp. z o.o.

AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

AUTODNA Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez AUTODNA Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.

**autoDNA**


Raport Historii Pojazdu autoDNA



Zeskanuj mnie!


KMHSW81UDHU732057

Hyundai SANTA FE



#### Jak skanować QR kod

Uruchom aparat w swoim telefonie i skieruj obiektyw telefonu na kod QR. Telefon automatycznie zeskanuje QR kod. Alternatywnie, uruchom aplikację do skanowania QR i postępuj analogicznie.



#### Jak nakleić na szybę

Naklej na boczną szybę samochodu, po prawej lub lewej stronie. Nie rekomendujemy naklejania na przednią szybę, która ustawiona jest pod kątem przez co trudniej będzie zeskanować QR kod.



#### Jak umieścić zdjęcie w ogłoszeniu

Dodaj QR kod jako kolejne zdjęcie do swojego ogłoszenia. Popularne serwisy umożliwiają dodawanie zdjęcia w rozmiarze do 5 MB o rozdzielczości 1080 x 720 px. Plik, który otrzymałeś od nas wraz z zamówionym raportem spełnia te wymagania. Po prostu dodaj zdjęcie do galerii sprzedawanego pojazdu.