



Raport Historii Pojazdu autoDNA

Raport zawiera dostępne informacje na dzień: 2022-12-12 11:08:46 UTC +0100

Wersja językowa: PL

9940331c-ce682800-a0b6ef89-a2758823-51ee1c02



Kia SPORTAGE
U5YPC813DCL167130

Wiek pojazdu

Wg daty produkcji / roku modelowego

10

LAT(A)

11

MIES.

Data produkcji / Rok modelowy 2012

Wg pierwszej rejestracji pojazdu

10

LAT(A)

7

MIES.

Data pierwszej rejestracji 2012-05-08

1 6 0 5 6 7 km

Uwaga: Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

CENTRUM POWIADOMIEŃ

Bazy Skradzionych Pojazdów



Przeszukane bazy 12/12

Akcje serwisowe



Nie odnotowano

Informacje o pojeździe



Liczba wpisów 19

Dziennik użytkowania



Liczba wpisów 9

Historia cenowa



Liczba wpisów 1

Odczyty drogomierza



Liczba wpisów 9

Historia uszkodzeń

 Liczba wpisów 4

Wyposażenie

 Liczba wpisów 302


Archiwalne zdjęcia

 Liczba wpisów 68

Poprawność VIN

 Niedostępne

INFORMACJE O POJEŹDZIE

Producent
KIA**Typ paliwa**
DIESEL**Rok modelowy**
2012**Próbka koloru lakieru**
**Silnik**
2.0L DOHC TCI**Napęd**
4WD**Średnie spalanie [l/100km]**
8.22**Model**
SPORTAGE**Pojemność silnika [cm3]**
2000**Kod koloru lakieru**
1K**Kod koloru wnętrza**
WK**Typ skrzyni biegów**
AUTOMATYCZNA**Kod modelu**
SEURPSLZ10**Rodzaj nadwozia**
SUV**Kraj producenta**
KOREA POŁUDNIOWA**Kolor lakieru**
BLACK PEARL**Data produkcji**
2012**Skrzynia biegów**
6-BIEGOWA**Rynek przeznaczenia**
C07, GERMANY

AKCJE SERWISOWE



Nie odnotowano

BAZA SKRADZIONYCH POJAZDÓW

Przeszukane bazy 12

Odnnotowano 0

**Włochy**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Czechy**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Rumunia**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Litwa**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Słowenia**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Holandia**Ewidencja pojazdów skradzionych - Repozytoria
Crimimail oraz Stowarzyszenie Ubezpieczycieli

Nie odnotowano

**Kanada**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Słowacja**

Ewidencja pojazdów skradzionych - Policja



Nie odnotowano

**Szwecja**Ewidencja pojazdów skradzionych - Stowarzyszenie
Ubezpieczycieli

Nie odnotowano

**Norwegia**

Ewidencja pojazdów skradzionych - Ettersokt



Nie odnotowano

**Kaynine**Ewidencja przedmiotów skradzionych -
Kaynine(Niemcy)

Nie odnotowano

**Baza int.**Ewidencja pojazdów skradzionych - Niezależne
źródła internetowe

Nie odnotowano

HISTORIA POJAZDU

2022

09.07.2022

Odnnotowano cenę / wartość

67 900 PLN brutto

09.07.2022

Zgłoszono odczyt drogomierza

Stan drogomierza
99 999 km

23.06.2022

Ubezpieczenie pojazdu

Polisa ważna do 2023-06-22

Kraj Polska

23.06.2022

Pojazd zarejestrowany

Zarejestrowany na firmę lub organizację

Miejsce rejestracji kartuski, pomorskie

Używany, sprowadzony

Kraj poprzedniej rejestracji Niemcy

Homologowany fabrycznie

Kraj Polska

23.06.2022

Wykonano okresowe badanie techniczne

Stan drogomierza
103 647 km

Wynik Pozytywny

Termin badania technicznego 2023-06-23

Kraj Polska

2020

02.2020

Odnotowano szkodę na pojeździe

Kwota 2000 - 2500 EUR

Rezultat



USZKODZENIE WNĘTRZA



USZKODZENIE NADWOZIA

Grupa części

- Szyby

- Tapicerka

Kraj Niemcy



Strefa uszkodzenia

- Lewa strona

- Prawa strona

02.2020

Zgłoszono odczyt drogomierza

Stan drogomierza
80 500 km

2019

08.2019

Zgłoszono odczyt drogomierza

Stan drogomierza
74 500 km

08.2019

Odnotowano szkodę na pojeździe

Kwota 2500 - 3000 EUR


Rezultat



USZKODZENIE NADWOZIA

Grupa części

- Elementy karoserii zewnętrznej



Strefa uszkodzenia

- Przód
- Prawy przód
- Lewy przód
- Lewa strona
- Prawa strona
- Tył
- Lewy tył
- Prawy tył
- Centralna część

Kraj Niemcy

05.2019

Odnotowano szkodę na pojeździe

Kwota 500 - 750 EUR

Rezultat



USZKODZENIE NADWOZIA



Strefa uszkodzenia

- Prawa strona

Kraj Niemcy

05.2019

Zgłoszono odczyt drogomierza

Stan drogomierza
70 500 km

24.01.2019

Serwis pojazdu

24.01.2019

Zgłoszono odczyt drogomierza

Stan drogomierza
67 827 km

2017

05.2017

Odnotowano szkodę na pojeździe

Kwota **750 - 1000 EUR**

Rezultat



USZKODZENIE NADWOZIA

Grupa części

- Elementy karoserii zewnętrznej

Kraj **Niemcy**



Strefa uszkodzenia

- Lewa strona

2016

20.12.2016

Serwis pojazdu

20.12.2016

Zgłoszono odczyt drogomierza

Stan drogomierza
44 080 km

2014

22.05.2014

Serwis pojazdu

22.05.2014

Zgłoszono odczyt drogomierza

Stan drogomierza
13 341 km

2013

14.10.2013

Serwis pojazdu

14.10.2013

Zgłoszono odczyt drogomierza

Stan drogomierza
8 003 km

2012

08.05.2012

Pierwsza rejestracja pojazdu

30.04.2012

Rozpoczęcie okresu gwarancyjnego

08.03.2012

Pojazd wyprodukowany

DZIENNIK SPRAWDZEŃ

Data i czas	Rodzaj usługi	IP	Lokalizacja
--	--	--	--

WYPOSAŻENIE

RETRACTOR PRETENSIONER - ELECTRICAL TYPE8885A2	BACK LITE GLASS TYPE - PRIVACY(W/ HEATED)8712C2	SEAT WARMER (HEATER) - HIGH/LOW - SEESAW8839B2
SEAT WARMER (HEATER) - HIGH/LOW - SEESAW8873B2	CENTRAL DR LOCK/UNLOCK-DR"S & PA"S CTRL8131A2	STEER"G COLUMN-MANUAL TILT & TELESCOPIC5631A4
TAIL GATE FINISH"G-FORMED TYPE(PLASTIC)817AB3	TOOL SET & JACK LABEL - AUS+NEW ZEALAND529TA3	BLUE TOOTH (AUDIO)-W/ VOICE RECOGNITION9552A2
LUMBAR SUPPORT - MANUAL LUMBER SUPPORT8828A1	MUFFLER MAIN ASSY - SINGLE-BLACK PAINT2861A1	ANTENNA TELESCOPIC - ANTENNA ROOF TYPE9621G1
O.B.D(ON-BOARD DIAGNOSTICS) - E.O.B.D2845A2	ARM REST COVER"G - ARTIFICIAL LEATHER8236A3	RR WIPER - INTERMITTENT(NON VARIABLE)9871A1
BUTTON START - BUTTON W/ ILLUMINATED8196A2	FUNCTION - WASHER FLUID LEVEL SENSOR9852A1	T/F TYPE - ELECTRONIC ON-DEMAND TYPE473JA4
W/ STORAGE BOX ARM REST - STD(1 DIN)846BA1	UPR TRIM FINISH"G - PLASTIC (PAINT)8232A6	SHIFT LOCK SYSTEM - ELECTRONIC TYPE4503A2
FR SUSP TYPE - MACPH. W/COIL SPRING5411A1	AUTO LIGHT CONTROL SYSTEM - 1 STAGE9511A1	ESC (ELECTRONIC STABILITY CONTROL)5894A1
ENGINE PACKAGE - VGT LOW POWER ENG0091A6	VSM (VEHICLE STABILITY MANAGEMENT)589GA1	SPEAKER LOCATION TWEETER-FR DR UPR963KA1
SPEAKER LOCATION RR DR LOW-GENERAL963ZA1	AUTO CRUISE CONTROL - CONVENTIONAL9641A1	MAP POCKET FINISH"G - W/O T/C PILE8235A1
PANORAMA SUNROOF - POWER-ONE TOUCH816PA1	FR WIPER - INTERMITTENT(VARIABLE)9811A2	DRIVER'S SIDE - ELECTRIC HTD-CONV8763C4
A/REST COVER - ARTIFICIAL LEATHER84C3A4	W/S GLASS TYPE-TINTED (W/ S/BAND)8611B2	IGNITION ILLUMINATED - BULB TYPE8195A1

FR COOLER - DUAL FULL AUTO A/CON	9761A6	BODY CONTROL MODULE - BCM(ETACS)	9541A1	SPEAKER LOCATION FR DR - GENERAL	963CA1
RR SUSP TYPE - MULTI LINK-NORMAL	5511B1	FREQUENCY VIBRATION - AM9K/FM50K	9615A3	NAVIGATION SYSTEM(LOW) - EUROPE	9654A2
FULL SIZE 1EA - AL WHEEL & TIRE	5297A3	FUEL FILLER DR REL TYPE - CABLE	8152A3	PASS"S SIDE - ELECTRIC HTD-CONV	8762C4
PRE TENSIONER - ELECTRICAL TYPE	888AA2	P/WINDOW SW - ILLUMINATION(ALL)	824FC1	O/HEAD CONSOLE TYPE - STANDARD	9295A1
INSIDE HNDL OVER RIDE - ALL DR	8135A3	HAC (HILLSTART ASSIST CONTROL)	589HA1	CLOTH - L/CLOTH(CLOTH+LEATHER)	8811B3
ROOF TRIM MATERIAL - NON WOVEN	8531A5	HEAD REST - UP/DOWN & SLIDING	8854A5	AVERAGE FUEL CONSUMPTION(AFC)	965BA1
HEAD REST - UP/DOWN & SLIDING	8821A5	CIGAR LIGHTER - BLANK"G COVER	8445A3	VOICE RECOGNITION SYSTEM REMO	967FA1
FREQUENCY-SMART KEY - GENERAL	9545A3	RR PARK"G ASSIST SYSTEM(RPAS)	9571A3	BATTERY CAPACITY - 72AH (5HR)	3711B6
SEAT WARMER (HEATER) - ON/OFF	892WB1	FUEL TANK-CAPACITY - 58 LITER	3111B7	IMPACT SENS"G AUTO DR UNLOCKG	813BA1
6:4 SPLIT BACK FOLD"G - BACK	8912D1	LEVER FINISH"G - METAL PAINT	8262A3	ELECTRIC CHROMIC MIRROR TYPE	8511C1
DBC (DOWNHILL BRAKE CONTROL)	94J1A1	MLD"G-S/SILL - NATURAL COLOR	8772B2	SEAT BACK - SEAT BACK POCKET	886BA1
SIDE AIR BAG-FR - FR(THORAX)	5693A1	EMISSION REGULATION - EURO 5	2841B7	DBC (DOWNHILL BRAKE CONTROL)	589AA1
ENGINE GASKET - NON ASBESTOS	2111A2	TIRE PRESSURE LABEL - EUROPE	529AB1	UNDER COVER - W/O NOISE PAD	2911A2
RR HEATING DUCTS - 2ND SEAT	9741A1	BAS(BRAKE ASSISTANT SYSTEM)	5895A1	AL WHEEL 7.0J * 18 - A TYPE	5291XA
ELEC TYPE - SOFT TOUCH TYPE	9721D1	DR BELT LINE MLD"G - BRIGHT	8223A3	CLUSTER TYPE - CONVENTIONAL	9401C1
ID PLATE - GEN+MES TYPE(ID)	8649B6	F.F.H.S(FUEL FILTER HEAT"G)	3914A1	ESS (EMERGENCY STOP SIGNAL)	5896A1
PASSENGER SIDE - DEPOWERED	5692A3	RR QTR GLASS TYPE -PRIVACY	8791C1	FUEL TANK MATERIAL - STEEL	3113A1
CENTRAL T/GATE LOCK/UNLOCK	8177A1	PROJECTION-LOW BEAM-A TYPE	9211F1	VANITY MIRROR - GLASS TYPE	852CA1
FOB HOLDER W/O ILLUMINATED	8197A1	AVERAGE VEHICLE SPEED(AVS)	965CA1	P/WINDOW RR DR - NONE AUTO	824CA1
VANITY MIRROR - GLASS TYPE	8522A1	STORAGE BOX - W/O FLOCK"G	846FA2	P/WINDOW PA"S - NONE AUTO	824BA1
AT KNOB - LEATHER WRAPPED	4371B3	CHILD SAFETY RR DR LOCK"G	8136A1	SPEED SENS"G AUTO DR LOCK	813AA1

P/WINDOW DR"S - AUTO DOWN	824AA3	ADJUSTER - PUMP"G DEVICE	8825A4	O/SIDE TEMPERATURE GAUGE	972DA1
ANTI-CORROSION TREATMENT	8648A1	SINGLE BOOSTER - 11 INCH	5911A6	DRL - DEDICATED LED TYPE	9213A4
S/BELT HEIGHT ADJUSTMENT	888JA1	S/BELT HEIGHT ADJUSTMENT	888SA1	CUP HOLDER - FR(W/O ILL)	8462A1
DISTANCE TO EMPTY(D.T.E)	965AA1	MLD"G-WINDSHIELD - BLACK	8612A1	ABS (ANTI LOCK BRK SYS)	5891A2
DRIVER SIDE - DEPOWERED	5691A3	FR BRAKE - DISC-16 INCH	5811A5	ELECTRIC FOLD"G CONTROL	876MA1
SPEEDOMETER TYPE - KMPH	94M0A1	INTEGRATED - CLEAR LENS	9231B1	RR BRAKE - DISC-15 INCH	5812A8
INSTANT FUEL CONSUMPTIO	965EA1	TIRE MATERIAL - SILICA	5295A2	TIE DOWN HOOK(LASHING)	8642A1
LUGGAGE SIDE - PLASTIC	8571B1	PASSENGER"S SIDE - ELR	8884D1	LEVELING DEVICE - AUTO	921BA2
A/T POSITION INDICATOR	94C1A1	TRUNK LID(T/GATE) OPEN	94D7A1	RR DR GLASS - PRIVACY	8245A5
ACTIVE HEAD RESTRAINT	885CA1	235 TIRE - 235/55 R18	5293JD	RR SPOILER - W/O HMSL	8721A1
ACTIVE HEAD RESTRAINT	882BA1	S/ABSORBER TYPE - GAS	5512A2	FUNCTION - AIR FILTER	9714A1
S/ABSORBER TYPE - GAS	5412A2	KEYLESS ENTRY-B/ALARM	819AA1	ANCHOR PRE TENSIONER	888HA1
CONVENTIONAL - CLEAR	9221D1	TEMPERATURE UNIT - C	94N0A1	FR DR GLASS - TINTED	8241A2
FINISH"G - CR COAT"G	8261A4	H.M.S.L - T/GATE INR	8722A2	PTC HEATER_INT TYPE	9713A2
SEAT BACK - N/PUNCH	8575A3	ENGINE COVER - SEMI	2921A2	VANITY MIRROR COVER	852HA1
VANITY MIRROR COVER	852BA1	A' TYPE - CR COAT"G	8631A3	DRIVER"S SIDE - ELR	8881B1
GRAIN - METAL PAINT	8481A6	PASS"S - A LANGUAGE	569BD1	N/PUNCH - FLAT TYPE	8421D1
LENS TYPE - NON LED	8723A1	TRIP ODOMETER - LCD	940AA3	DIRECTION INDICATOR	94C6A1
CENTER TRIM - PAINT	8233L1	HOLDER - UPR ANCHOR	892DA1	BULB TYPE - 2 BULB	928WA2
FR - W/ SUNGLASSES	9282A1	BACK WARN"G CAMERA	9652A1	EXTERNAL AMP - AMP	963WA1
COLOR - BODY COLOR	8765A2	SIDE REPEATER LAMP	876NA1	MLD"G-ROOF - BLACK	8725A1

RR HEATED W/ TIMER	871BA1	SEAT BELT REMINDER	8889A1	SEAT BELT REMINDER	888DA1
COLOR - BODY COLOR	8652B1	KICKDOWN MECHANISM	327AA1	DR AJAR - DR AJAR	94DOA1
BLADE TYPE - AERO	9819A2	4-SPOKE - LEATHER	5611C3	FORMED TYPE - STD	8231B1
PAB ON/OFF SWITCH	569EA1	RR - CONVENTIONAL	9222A1	GLOVE BOX-COOLING	845DA1
SEAT BACK POCKET	8836A1	COMPONENT- 2 DIN	9614B1	MATERIAL - VINYL	8523A1
MAP POCKET-RR DR	82A7A1	FR IMPACT SENSOR	569CA1	MATERIAL - VINYL	8521A1
LUGGAGE NET HOOK	8578A1	CTR - DELAY LAMP	928FA3	ACTIVE ECO - S/W	94X9A1
MAP POCKET-FR DR	82A5A1	TYPE - EXTENSION	852EA1	TYPE - EXTENSION	852LA1
SPEAKER - WOOFER	963SA1	IGN KEY REMINDER	813DA1	FR WIPER-2 SPEED	981AA1
ELAPSE TIME(E/T)	965DA1	DOUBLE RECLIN"G	8824A2	PAB ON/OFF LAMP	569JA1
SW ILLUMINATION	8133A1	WATER SEPARATER	94H2A1	LUGGAGE SIDE LH	857FA1
ROLLOVER SENSOR	569HA1	W/ SUNGLASS BOX	9298A1	CLUSTER IONIZER	9717A1
TYPE - 2.5 MILE	8651B1	DOUBLE RECLIN"G	885EA2	SMART KEY-FR DR	819HA1
W/ WIPER DEICER	86A1A1	S/BELT REMINDER	898JA1	DOUBLE RECLIN'G	8922A2
FLOOR - N/PUNCH	8573A3	CRUISE CONTROL	94F3A1	AMS - W/ MICOM	3731A2
GLOW INDICATOR	94G5A1	FR - REFLECTOR	928HA2	TYPE - FOLDING	8194B3
A PILLAR - STD	858AA1	B PILLAR - STD	858BA1	C PILLAR - STD	858CA1
D PILLAR - STD	858EA1	DR SCUFF - STD	858RA1	LUGGAGE SCREEN	857IA1
BATTERY CHARGE	94D1A1	TYPE - DIGITAL	9451A1	HOOD INSULATOR	811AA1
BATTERY SAVER	371CA1	HORN - SINGLE	9661A1	W/ SUNROOF SW	9299A1
ECO INDICATOR	94X2A1	TICKET HOLDER	852AA1	WHL ARCH MLDG	877FA1


ENG OIL LEVEL	94H8A1	CURTAIN A/BAG	5695A1	MLD"G - BLACK	8731A1
H/LAMP WASHER	9214A1	FOG LAMP (FR)	94G4A1	REMOTE FOLD"G	89E4A1
CORNER"G LAMP	928TA1	LOAD LIMITER	888EA1	LOAD LIMITER	889MA1
RR DEFLECTOR	877BA1	DRINK HOLDER	89C1A1	LUGGAGE LAMP	9287A1
OIL PRESSURE	94C7A1	CHECK ENGINE	94D9A1	POWER OUTLET	846EA1
BRAKE VACUUM	94H1A1	PARK"G BRAKE	94C9A1	ILLUMINATED	852DA1
RR FOG LAMP	94D5A1	GRADE - GLS	863CA2	TOWING HOOK	8641A1
IMMOBILIZER	94H6A1	AUDIO REMO.	967AA1	HID (XENON)	9216A1
LUGGAGE NET	8579A1	RAIN SENSOR	9815A1	ILLUMINATED	852KA1
IMMOBILIZER	9542A1	SPEEDOMETER	9402A1	W/ MAP LAMP	9297A1
WINDOW TRIM	817BA1	WATER TEMP.	940DA1	4WD LOCKING	940JA1
SET CONTROL	94F4A1	STEP PLATE	858SA1	LWR ANCHOR	892GA1
SIDE - ELR	8981A4	TACHOMETER	940BA1	HIGH GRADE	6501A1
IPOD CABLE	961EA1	SEAT BELT	9681A1	E.S.P OFF	94J0A1
RR - 2 EA	853AA2	FR - 1 EA	8532A1	BRAKE OIL	94C8A1
FATC TYPE	972AA1	ACC REMO.	967BA1	ROOF RACK	8672A1
CTR - ELR	8982A4	SEAT BELT	94E3A1	W/ DAMPER	8452A2
HIGH BEAM	94D2A1	RR - 2 EA	853JA2	LOW BEAM	94D3A1
W/ ILLUM	845BA1	RHEOSTAT	9491A1	LOW FUEL	94D4A1
KEY OUT	94V1A1	FOB KEY	819GA1	H-MATIC	4509A1
W/O BOX	89B1A1	SLIDING	885DA1	SLIDING	8823A1

USB+AUX	9618A1	ESCORT	921JA1	CLEAR	9241A1
E.S.P	94H9A1	A/BAG	94E6A1	A.B.S	94E5A1
FUEL	940CA1	MDPS	5711A6	MDPS	94H7A1
CTR	8915A1	4WD	940KA1	RH	8914A1
LH	8913A1	Opis --	WT 3		

ARCHIWALNE ZDJĘCIA POJAZDU

10.07.2022

Liczba zdjęć 34









09.07.2022

Liczba zdjęć 34









Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez AUTODNA Sp. z o.o. o tym fakcie. AUTODNA Sp. z o.o. nie ponosi odpowiedzialności za treść danych zawartych w Raportach. Treść taka może być niepełna lub niezgodna ze stanem rzeczywistym.

Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody AUTODNA Sp. z o.o.

AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

AUTODNA Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez AUTODNA Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.

autoDNA


Raport Historii Pojazdu autoDNA



Zeskanuj mnie!


U5YPC813DCL167130

Kia SPORTAGE



Jak skanować QR kod

Uruchom aparat w swoim telefonie i skieruj obiektyw telefonu na kod QR. Telefon automatycznie zeskanuje QR kod. Alternatywnie, uruchom aplikację do skanowania QR i postępuj analogicznie.



Jak nakleić na szybę

Naklej na boczną szybę samochodu, po prawej lub lewej stronie. Nie rekomendujemy naklejania na przednią szybę, która ustawiona jest pod kątem przez co trudniej będzie zeskanować QR kod.



Jak umieścić zdjęcie w ogłoszeniu

Dodaj QR kod jako kolejne zdjęcie do swojego ogłoszenia. Popularne serwisy umożliwiają dodawanie zdjęcia w rozmiarze do 5 MB o rozdzielczości 1080 x 720 px. Plik, który otrzymałeś od nas wraz z zamówionym raportem spełnia te wymagania. Po prostu dodaj zdjęcie do galerii sprzedawanego pojazdu.